### LOAN DOCUMENT

	PHOTOGRAPH THIS	SHEET
ION NUMBER	LEVEL	INVENTORY
DTIC ACCESSION NUMBER	Bioventing Pilit Test  DOCUMENT IDENTIFICATION  MAY 94	H
	DISTRIBUTION STA Approved for Public Distribution Unl	Release D
	DISTRIBUTI	ON STATEMENT L
BY  DISTRIBUTION  DISTRIBUTION  DISTRIBUTION AVAILABILITY AND/OR SPECIAL  DISTRIBUTION STAMP		DATE ACCESSIONED  DATE ACCESSIONED  C A R
	•	
	*	E
		DATE RETURNED
20001214	010	
DATE REC	EIVED IN DITIC	REGISTERED OR CERTIFIED NUMBER
	PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-F	DAC
DTIC ANN 70A	DOCUMENT PROCESSING SHEET	PREVIOUS EDITIONS MAY BE USED UNTIL

LOAN DOCUMENT

## DRAFT

Bioventing Pilot Test Work Plan For Facilities 1748, 44625D, and 44625E Cape Canaveral AFS, Florida

### **PART II**

Draft Interim Pilot Test Results Report for Facilities 1748, 44625D, and 44625E Cape Canaveral AFS, Florida

**Prepared For** 

Air Force Center for Environmental Excellence Brooks AFB, Texas

and

45 CES/CEV Patrick AFB, Florida

ES

Engineering-Science, Inc.

May 1994

1700 BROADWAY, SUITE 900 DENVER, COLORADO 80290



	DEFENSE TECHNICAL INFORMATION CENTER REQUEST FOR SCIENTIFIC AND TECHNICAL REPORTS						
Tit	AFCEE Collection						
	SHILLING THE STATE OF THE STATE						
	Report Availability (Please check one box)  This report is available. Complete sections 2a - 2f.	2s. Nur Copies I	nger or Forwarded	2b. Forwarding Date			
	This report is not available. Complete section 3.	10	ach	0,10/2001			
Źc.	. Distribution Statement (Please check ONE DOX)	12	acro	July 2000			
	Directive 5230.24, "Distribution Statements on Technical Documents cribed briefly below. Technical documents MUST be assigned a distrib			n distribution statements, as			
M	DISTRIBUTION STATEMENT A: Approved for public rel	lease. Di	stribution is u	infimited.			
	DISTRIBUTION STATEMENT B: Distribution authorized	to U.S. C	Sovernment /	Agencies only.			
	DISTRIBUTION STATEMENT C: Distribution authorized contractors.	1 to U.S. C	Sovernment :	Agencies and their			
	DISTRIBUTION STATEMENT D: Distribution authorized DoD contractors only.	to U.S. C	)epartment o	f Defense (DoD) and U.S			
I	DISTRIBUTION STATEMENT E: Distribution authorized components only.	to U.S. C	Department o	f Defense (DoD)			
	DISTRIBUTION STATEMENT F: Further dissemination indicated below or by higher authority.	only as di	racted by the	controlling DoD office			
	DISTRIBUTION STATEMENT X: Distribution authorized individuals or enterprises eligible to obtain export-control Directive 5230.25, Withholding of Unclassified Technical	led techni	ical data in a	ccordance with DoD			
	P			The state of the s			
2d. Reason For the Above Distribution Statement (in accordance with BoD Directive 5230.24)							
2e.	Controlling Office		Date of Distr	ibution Statement			
	HQ AFLEE			2000			
<b>3</b> . '	This report is NOT forwarded for the following reason:	s. (Please	check appropri	ate box)			
	It was previously forwarded to DTIC on (d	late) and it	ne AD numbs	ris			
	It will be published at a later date. Enter approximate dat	te if know	77.	ng dan tanàna sakana makana makana ng bagahan tanàna an mana sa mana sa ma			
	in accordance with the provisions of DoD Directive 3200, because:	12, the ra	quasted dec	ument is not supplied			
	* ************************************		\$23997355524544444444444483333 8864444444444444444444	**************************************			
	GD3B4194B4B4AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	man paning a constitutiva en man a	*/\$>>>\$777269848873829\$E>*******				
Prin	nt or Type Name Signal	pre					
La	aphone Place	acci	For one Said	The state of the s			
21	10-536-1431			101-03-0431			

#### PART I

### BIOVENTING PILOT TEST WORK PLAN FOR FACILITIES 1748, 44625D, AND 44625E

#### CAPE CANAVERAL AFS, FLORIDA

November 1993

#### Prepared for:

Air Force Center for Environmental Excellence Brooks AFB, Texas

and

45 CES/CEV

Patrick AFB, Florida

Prepared by:

Engineering-Science, Inc. 1700 Broadway, Suite 900 Denver, Colorado 80290

#### TABLE OF CONTENTS

1.0	Introducti	on	1
2.0	Site Descr	iption	2
	2.1 Lo	cation and History	2
	2.1.1	Location and History for Facility 1748	2
	2.1.2	Location and History for Facilities 44625D and 44625E	6
	2.2 Site	e Geology	6
		Geology for Facility 1748	
	2.2.2	Geology for Facilities 44625D and 44625E	10
	2.3 Site	e Contaminants	10
	2.3.1	Contaminants for Facility 1748	10
	2.3.2	Contaminants for Facilities 44625D and 44625E	10
3.0	Pilot Test	Activities	11
٥.0		roduction	
		ell Siting and Construction	
		Well Siting and Construction for Facility 1748	
		Well Siting and Construction for Facilities	11
	5.2.2	44625D and 44625E	13
	3.3 Ha	ndling of Soil Boring Cuttings and Excavated Soils	
		l and Soil Gas Sampling	
		Soil Sampling	
		Soil Gas Sampling	
	3.5 Air	Monitoring	19
		ower System	
	3.7 In	Situ Respiration Test	19
	3.8 Air	Permeability Test	21
	3.9 Ins	tallation of Extended Pilot Test Bioventing System	21
4.0	Exception	s to Protocol Procedures	21
5.0	Base Supp	oort Requirements	22
		st Preparation	
6.0	Project Sc	hedule	23

7.0 Points of Contact	24
8.0 References	24
FIGURES	
Figure 2.1 Facility 1748 Site Plan.	3
Figure 2.2 Facility 1748 Soil Gas Survey Locations	4
Figure 2.3 Facilities 44625D and 44625E Site Plan	7
Figure 2.4 Facilities 44625D and 44625E Soil Gas Survey Locations	8
Figure 3.1 Facility 1748 Bioventing Pilot Test Site Plan	12
Figure 3.2 Proposed Injection Vent Well Construction	14
Figure 3.3 Monitoring Point Construction Detail	15
Figure 3.4 Facilities 44625D and 44625E Bioventing Pilot Test Site Plan	16
Figure 3.5 Blower System Instrumentation Diagram for Air Injection	20
TABLES	
Table 2.1 Soil Gas Survey Results, Facility 1748	
Table 2.2 Soil Gas Survey Results, Facilities 44625D and 44625E	9

#### DRAFT

#### BIOVENTING TEST WORK PLAN FOR FACILITY 1748 (BASE CAFETERIA) AND FACILITY 44625D AND FACILITY 44625E (GENERATOR MAINTENANCE SHOP) CAPE CANAVERAL AFS, FLORIDA

#### 1.0 INTRODUCTION

This site-specific work plan presents the scope of multi-phase bioventing pilot tests for *in-situ* treatment of fuel-contaminated soils at the base cafeteria, designated as Facility 1748 and two contaminated areas at the generator maintenance shop, designated as Facility 44625D and 44625E at Cape Canaveral Air Force Station (AFS), Florida. The proposed pilot tests will be performed by Engineering-Science, Inc. (ES). The three primary objectives of the proposed pilot tests are: 1) to assess the potential for supplying oxygen throughout the contaminated soil depth within the unsaturated zone, 2) to determine the rate at which indigenous microorganisms will degrade the fuel when stimulated by oxygen-rich soil gas, and 3) to evaluate the potential for sustaining these rates of biodegradation until fuel contamination is remediated to concentrations below regulatory standards.

If bioventing proves to be a feasible technology for these sites, pilot test data may be used to design a full-scale remediation system and to estimate the time required for remediating soils to regulatory standards. An added benefit expected from the pilot testing at these areas is that a significant amount of the fuel contamination should be biodegraded during the 1-year pilot test, as the testing will take place within the most contaminated soils that have been detected at the site.

The pilot tests will utilize one vertical air injection vent well (VW) at each facility. Each site will be equipped with a blower capable of sustaining a flow rate of 20 to 40 standard cubic feet per minute (scfm). VW tests typically produce an effective radius of influence of approximately 20 to 40 feet. The design air injection rate and actual radius of influence for the sites will depend on soil properties and other factors. Rates of *in situ* fuel biodegradation will be determined for individual soil vapor monitoring points (VMPs) that will be installed around the VWs.

Additional background information on the development and recent success of the bioventing technology is found in the protocol document entitled *Test Plan and* 

Technical Protocol for a Field Treatability Test for Bioventing (Hinchee et. al. 1992). This protocol document is a supplement to the site-specific work plan and it will also serve as the primary reference for pilot test VW and VMP designs, and detailed test objectives and procedures. Unless otherwise noted, test procedures outlined in the protocol document will be used during the pilot test at Facilities 1748, 44625D, and 44625E.

#### 2.0 SITE DESCRIPTION


#### 2.1 Location and History

#### 2.1.1 Location and History for Facility 1748

Facility 1748 (the base cafeteria) is located on Hangar Road within the industrial area on CCAFS (Figure 2.1). This facility has been in operation since 1958. A 4,000-gallon underground diesel fuel tank was installed in 1958 to fuel the boilers used by the base cafeteria and remained in service until March 1992.

A Phase I Assessment conducted in March 1992 at Facility 1748 in the vicinity of the out-of-service 4,000-gallon diesel underground storage tank (UST) indicated the presence of hydrocarbon soil contamination in the area adjacent to the UST (CH<sub>2</sub>M Hill, 1992). Figure 2.2 depicts the estimated limits of excessively contaminated soil above the water table in the vicinity of the UST location at Facility 1748, as determined during the March 1992 assessment. Excessive soil contamination was determined using the guidelines approved by the State of Florida in accordance with the Florida Administrative Code (F.A.C.) Chapter 17-770. The study also indicated, based on interviews with station personnel, that the petroleum contamination was likely a result of historical overfilling of the tank. The significant hydrocarbon soil contamination found at this site is the primary target for bioventing treatment.

A soil gas survey was conducted by ES at Facility 1748 in July 1993. A 20x25-foot grid was laid out in the field where previous sampling determined significant hydrocarbon soil contamination. Oxygen (O<sub>2</sub>), carbon dioxide (CO<sub>2</sub>), and total volatile petroleum hydrocarbon (TVPH) measurements were collected at depths of 2.5 and 5.0 feet below ground surface (bgs), at five grid locations. Based on the results of the survey, significant soil contamination still exists within the area surveyed. Figure 2.2 presents the soil gas survey point locations. Table 2.1 presents the results of the soil gas survey.






TABLE 2.1 SOIL GAS SURVEY RESULTS FACILITY 1748 CAPE CANAVERAL AIR FORCE STATION, FLORIDA

July 1993 SG-1 2.5 8.2 8.2 8.6 0.5 8.6 0.5 8.7 8.8 8.7 8.0 0.0 8G-3 2.5 17.0 8G-4 2.5 0.0 8G-5 8.0 8G-5 8.0 8G-5 8.0 8G-5 8.0 8G-5 8.0 8G-5 8.0 8.0 8G-5 8.0 8.0 8.0 8G-5 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0 8.0	Soil Gas Test Point (f	Depth feet bgs) <sup>a</sup> /	O <sub>2</sub> (percent)	CO <sub>2</sub> (percent)	TVPH Concentration (ppmv) <sup>b</sup> /	Remarks
SG-2 2.5 SG-3 2.5 SG-4 2.5 SG-5 5.0 SG-5 5.0	SG-1	2.5	8.2	10.0	240	Water table
2.5.5 2.5.0 2.5.0 2.5.0 5.0		5.0	0.5	16.0	1,600	$\sim 6.5$ ft bgs
5.0 5.0 5.0 5.0 5.0 5.0	SG-2	2.5	7.8	10.2	260	
2.5 2.5 2.5 2.5 2.5		5.0	0.0	16.5	360	
5.0 5.0 2.5 5.0	SG-3	2.5	17.0	3.3	140	
2.5 5.0 2.5		5.0	15.9	3.9	140	
5.0 2.5	SG-4	2.5	0.0	16.0	16,600	
2.5		5.0	0.0	16.5	>20,000	
1	SG-5	2.5	0.0	17.5	> 20,000	
		5.0	0.0	18.0	> 20,000	

a/ Below ground surface (bgs)

b/ TVPH = Total volatile petroleum hydrocarbons; ppmv = parts per million, volume per volume

#### 2.1.2 Location and History for Facilities 44625D and 44625E

Facilities 44625D and 44625E (generator maintenance facility) is located within the industrial area on CCAFS (Figure 2.3). These facilities have been in operation since 1974. According to Base personnel a 1,000-gallon underground waste oil tank was installed in 1965 adjacent to Facility 44625D.

A Phase I Assessment was conducted in January, 1992 at Facilities 44625D and 44625E in the vicinity of the former 1,000-gallon underground waste oil tank. Results from the assessment indicated the presence of hydrocarbon soil contamination in the area adjacent to the tank. Figure 2.4 depicts the estimated limits of visually-stained soil, above the water table, at Facilities 44625D and 44625E (CH<sub>2</sub>M Hill, 1992).


According to the Phase I report, the 1,000-gallon underground waste oil tank was removed in August 1991 and replaced with an above-ground waste oil tank. According to station personnel, a visually stained seam of soil was evident along the northeast face of the open excavation during the tank removal. Station personnel also reported that the ground surface in this area had been subject to numerous past surface spills and leaks of petroleum products (CH<sub>2</sub>M Hill, 1992). The presence of hydrocarbon soil contamination, like that found at this site, is the primary target for bioventing treatment.

A soil gas survey was conducted by ES at Facilities 44625D and 44625E in July, 1993. Eight total soil gas locations were sampled; four locations associated with Facility 44625D and four at Facility 44625E. All soil gas sampling locations were located within the areas where previous sampling indicated visually stained hydrocarbon soil contamination. Oxygen (O<sub>2</sub>), carbon dioxide (CO<sub>2</sub>), and total volatile petroleum hydrocarbon (TVPH) measurements were collected at depths of 2.5 and 5.0 feet bgs at all eight soil gas locations. Based on the results of the survey, significant soil contamination still exists within the two areas surveyed. Figure 2.4 presents the soil gas survey point locations. Table 2.2 presents the results of the soil gas survey which show anaerobic soil conditions and indicate a need for bioventing.

#### 2.2 Site Geology

#### 2.2.1 Geology for Facility 1748

Because the bioventing technology is applied to the unsaturated soils, this section will primarily address soils above the shallow aquifer. Soils at this site and to a depth of 40 feet bgs consist of predominantly unconsolidated, moderately well-sorted, fine-to-course-grained quartz sand with few to many shell fragments.






TABLE 2.2 SOIL GAS SURVEY RESULTS FACILITY 44625D and 44625E CAPE CANAVERAL AIR FORCE STATION, FLORIDA

Date	Soil Gas Test Point	Depth (feet bgs) <sup>a</sup> /	O <sub>2</sub> (percent)	CO <sub>2</sub> (percent)	TVPH Concentration (ppmv) <sup>b</sup> /	Remarks
Facility 44625D July 1993	SG-1	2.5	12.8	6.8	200	Water table $\sim 6.5$ ft bgs
D	SG-2	2.5	2.7	13.5	280 880 880	
	SG-3	2.5	0.0	15.0	2,200	
	SG-4	2.5 5.0	0:00	14.8	2,800	
Facility 44625E July 1993	SG-1 SG-3 SG-4	2.5 5.0 5.0 5.0 5.0 5.0	0.0 0.0 0.0 0.0 0.0 0.0	15.0 16.0 15.0 16.0 12.2 15.8 14.7	280 880 14,600 14,800 360 6,400 4,200 5,600	Water table ~ 6.5 ft bgs

a/ Below ground surface (bgs)

b/TVPH = Total volatile petroleum hydrocarbons; ppmv = parts per million, volume per volume

Groundwater is encountered at fluctuating depths of approximately 6 to 8 feet across the site. The generally homogeneous, sandy material at this site appears to be well suited to bioventing treatment.

#### 2.2.2 Geology for Facilities 44625D and 44625E

Because the bioventing technology is applied to the unsaturated soils, this section will primarily address soils above the shallow aquifer. Soils at this site and to a depth of 40 feet bgs consist of predominantly unconsolidated, moderately well-sorted, fine-to-course-grained quartz sand with up to 40 percent shells and shell fragments. Groundwater is encountered at fluctuating depths of approximately 6 to 8 feet. The generally homogeneous, sandy material at this site appears to be well suited to bioventing treatment.

#### 2.3 Site Contaminants

#### 2.3.1 Contaminants for Facility 1748

The primary contaminants at Facility 1748 are petroleum hydrocarbons (diesel fuel), which have been detected in the soils above the shallow aquifer. Excessively contaminated soils have been detected in the surface soils sampled at a depth between 2 and 6 feet bgs. Samples from the 1991 soil borings collected in the vicinity of the out-of-service diesel UST and above the shallow aquifer showed excessively contaminated soil concentrations ranging from 100 parts per million (ppm) to > 1,000 ppm. The soil samples, collected during the Phase I Assessment, were screened in the field for petroleum hydrocarbons using an organic vapor analyzer (OVA), equipped with a flame ionization detector (FID). Soil contaminated by diesel fuel is considered to be excessively contaminated if the concentration of total hydrocarbon vapor from a headspace analysis is 50 ppm or greater when using an OVA-FID (CH<sub>2</sub>M Hill, 1992).

#### 2.3.2 Contaminants for Facilities 44625D and 44625E

The primary contaminants at Facilities 44625D and 44625E are petroleum hydrocarbons, which have been detected in the soils above the shallow aquifer. Excessively contaminated soil was observed during a preliminary soils investigation conducted in 1991. Samples from the 1991 soil borings collected in the vicinity of the former 1,000-gallon waste oil tank and in the unsaturated soils showed elevated headspace concentrations of total hydrocarbons ranging from 64 ppmv to >1,000 ppmv. The soil samples were screened in the field using an OVA-FID (CH<sub>2</sub>M Hill, 1992). Soil contaminated by waste oil is considered excessively contaminated when it appears petroleum saturated by visually observable staining.

#### 3.0 PILOT TEST ACTIVITIES

#### 3.1 Introduction

The purpose of this section is to describe the proposed location for one VW and three VMPs at each of the following facilities: 1748, 44625D, and 44625E. Soil sampling procedures and the blower configuration that will be used to inject air (oxygen) into the contaminated soils are also discussed in this section. Pilot test activities will be confined to the unsaturated soils. No dewatering will take place during the pilot tests. Existing monitoring wells located in uncontaminated soils which have a portion of their screened interval above the water table may be used as a background monitoring point (MP) to measure the composition of background soil gas.


#### 3.2 Well Siting and Construction

#### 3.2.1 Well Siting and Construction for Facility 1748

A general description of criteria for siting the VW and associated VMPs are included in the protocol document. Figure 3.1 illustrates the proposed location of the VW and VMPs at Facility 1748. These locations were selected based on previous analytical data collected at the site, and the soil gas survey conducted in July 1993.

The analytical data shows elevated hydrocarbon contamination extending from ground surface to the groundwater table in the vicinity of the out-of-service 4,000-gallon diesel UST. This area is expected to have a high average TPH concentration, based on previous soil sampling in the area. The soil gas survey conducted in this area showed the soils to be oxygen depleted (<2%), contain high TVPH concentrations (>20,000 ppmv) and elevated CO<sub>2</sub> (>15%). Increased biological activity should be stimulated by oxygen-rich soil gas ventilation during pilot test operations. Final location of the VWs may vary slightly from the proposed locations if significant soil contamination is not observed during the well installation boring.

Due to the relatively shallow depth of unsaturated soil contamination at this site (<8 feet bgs) and the potential for moderately permeable soil conditions, the radius of venting influence around the VWs is expected to approach 40 feet. A total of three VMPs will be located within a 10-foot, 20-foot, and 30-foot radius of the VW.



Additionally, the well will be used to determine if natural carbon sources are contributing to oxygen uptake during the *in situ* respiration test. Additional details on the *in situ* respiration test are found in Section 5.7 of the protocol document.


The VW will be constructed of 4-inch inside diameter Schedule 40 PVC, with a five foot interval of 0.03 slotted screen set between 3 and 8 feet bgs (the deepest seasonal groundwater elevation expected). Flush-threaded PVC casing and screen will be used with no organic solvents or glues. The filter pack will be clean, graded 6/20 course silica sand, and will be placed in the annular space of the screened interval. A 2-foot layer of bentonite will be placed directly over the filter pack. The first foot of bentonite will consist of bentonite pellets hydrated in place with potable water. This layer of pellets will prevent the addition of the bentonite slurry from saturating the filter pack. The remaining one foot of bentonite will be fully hydrated and mixed above ground and the slurry tremied into the annular space to produce an air tight seal above the screened interval. Then, a one foot layer of cement/bentonite grout will be placed on top of the bentonite slurry to complete the seal to ground surface. A complete seal is critical to prevent injected air from short-circuiting to the surface during the bioventing test. Figure 3.2 illustrates the proposed VW construction details for this site.


A typical single-depth vapor monitoring point (VMP) installation for this site is shown in Figure 3.3. Because of the rather shallow depth to groundwater, only one air monitoring point will be required for each location. Soil gas oxygen and carbon dioxide concentrations will be monitored at a depth interval of approximately 3.0 to 3.5-feet at each location. Monitoring will confirm that the soil is receiving sufficient oxygen and will be used to measure fuel biodegradation rates. As with the VW, several inches of bentonite pellets will be used to shield the filter pack from rapid infiltration of bentonite slurry additions. Additional details on VW and monitoring point construction are found in Section 4 of the protocol document.

#### 3.2.2 Well Siting and Construction for Facility 44625D and 44625E

A general description of criteria for siting the VW and associated VMPs are included in the protocol document. Figure 3.4 illustrates the proposed location of the VW and VMPs at Facilities 44625D and 44625E. These locations were selected based on available analytical data and the soil gas survey conducted in July 1993.

The analytical data shows elevated hydrocarbon contamination extending from ground surface to the groundwater table in the vicinity of each facility. This area is expected to have a high average TPH concentration, based on previous soil






DRAWING IS NOT TO SCALE

PROPOSED MONITORING POINT CONSTRUCTION DETAIL

CAPE CANAVERAL, FLORIDA

ENGINEERING-SCIENCE, INC Orlando, Florida





sampling in the area. The soil gas survey conducted in this area showed the soils to be oxygen depleted (<2%), contain high TVPH concentrations (>2,000 ppmv at Facility 44625D and >14,000 ppmv at Facility 44625E) and elevated CO<sub>2</sub> (>12%). Increased biological activity should be stimulated by oxygen-rich soil gas ventilation during pilot test operations. Final location of the VWs may vary slightly from the proposed locations if significant soil contamination is not observed during the well installation boring.

Due to the relatively shallow depth of unsaturated soil contamination at this site (<8 feet bgs) and the potential for moderately permeable soil conditions, the radius of venting influence around the VWs is expected to approach 40 feet. A total of three VMPs will be located within a 10-foot, 20-foot, and 30-foot radius of the VW. A single permanent background monitoring point will be installed in uncontaminated soils to measure background levels of oxygen and carbon dioxide. Additionally, the single background well will be used by all three sites to determine if natural carbon sources are contributing to oxygen uptake during the *in situ* respiration test. Additional details on the *in situ* respiration test are found in Section 5.7 of the protocol document.

The VW will be constructed of 4-inch inside diameter Schedule 40 PVC, with a five foot interval of 0.03 slotted screen set between 3 and 8 feet bgs (the deepest seasonal groundwater elevation expected). Flush-threaded PVC casing and screen will be used with no organic solvents or glues. The filter pack will be clean, graded 6/20 course silica sand, and will be placed in the annular space of the screened interval. A 2-foot layer of bentonite will be placed directly over the filter pack. The first foot of bentonite will consist of bentonite pellets hydrated in place with potable water. This layer of pellets will prevent the addition of the bentonite slurry from saturating the filter pack. The remaining one foot of bentonite will be fully hydrated and mixed above ground and the slurry tremied into the annular space to produce an air tight seal above the screened interval. Then, a one foot layer of cement/bentonite grout will be placed on top of the bentonite slurry to complete the seal to ground surface. A complete seal is critical to prevent injected air from short-circuiting to the surface during the bioventing test. Figure 3.2 illustrates the proposed VW construction details for this site.

A typical single-depth vapor monitoring point (VMP) installation for this site is shown in Figure 3.3. Because of the rather shallow depth to groundwater, only one air monitoring point will be required for each location. Soil gas oxygen and carbon dioxide concentrations will be monitored at a depth interval of approximately 3.0 to 3.5-feet at each location. Monitoring will confirm that the soil is receiving sufficient

oxygen and will be used to measure fuel biodegradation rates. As with the VW, several inches of bentonite pellets will be used to shield the filter pack from rapid infiltration of bentonite slurry additions. Additional details on VW and monitoring point construction are found in Section 4 of the protocol document.

#### 3.3 Handling of Soil Boring Cuttings and Excavated Soils

Cuttings from all soil borings and any remaining waste soils will be collected in a Department of Transportation (DOT)-approved container. The containers will be labeled and then placed in a designated Cape Canaveral AFS hazardous materials storage area. These waste soils will become the responsibility of Cape Canaveral AFS and will be analyzed, handled, and disposed of in accordance with the current procedures for ongoing remedial investigations. This project is expected to generate less than four 55-gallon drums of waste soils.

#### 3.4 Soil and Soil Gas Sampling

#### 3.4.1 Soil Sampling

A total of three soil samples will be collected from each of the pilot test areas during the installation of the VWs and VMPs. Sampling procedures will follow those outlined in the protocol document, with minor modifications for the collection of one sample from the most contaminated interval of the VW installation. One sample will be collected from the interval of highest apparent contamination in two of the borings for the VMPs at each facility. Soil samples will be analyzed for TRPH, BTEX, soil moisture, pH, particle sizing, alkalinity, total iron, and nutrients.

Samples will be obtained by hand augering to the desired sampling depth and then collecting the required volume of soil directly from the hand auger bucket. A photoionization detector (PID) or total hydrocarbon vapor analyzer (see protocol document Section 4.5.2) will be used to screen the hand auger cuttings for intervals of high fuel contamination. Additionally, the PID will be used to ensure that breathing-zone levels of volatiles do not exceed 1 part per million, per volume (ppmv) while conducting soil borings and well installations. Soil samples collected will be immediately placed in laboratory-prepared containers. Samples will be labeled following the nomenclature specified in the protocol document (Section 5.5) and placed in an ice chest maintained at a temperature of 4° Celsius for shipment. A chain-of-custody form will be filled out, and the ice chest shipped to Pace, Inc. laboratory in Huntington Beach, California for analysis. This laboratory has been audited by the U.S. Air Force and meets all quality assurance/quality control and certification requirements for the State of California.

#### 3.4.2 Soil Gas Sampling

A total of nine initial soil gas samples will be collected in SUMMA<sup>TM</sup> cannisters in accordance with the *Bioventing Field Sampling Plan* (Engineering-Science, Inc., 1992). The samples will be collected from the VW, and one each from the VMPs closest to and furthest from the VW at each facility. These soil gas samples will be used to predict potential air emissions, to determine the reduction in BTEX and total volatile hydrocarbons (TVH) during the 1-year test, and to detect any migration of these vapors from the source area.

Soil gas sample canisters will be placed in a small cooler and packed with foam pellets to prevent excessive movement during shipment. Samples will not be sent on ice to prevent condensation of hydrocarbons. A chain-of-custody form will be filled out, and the cooler will be shipped to the Air Toxics laboratory in Folsom, California for analysis.

#### 3.5 Air Monitoring

The bioventing technique will minimize the loss of volatiles to the atmosphere by reducing air injection rates to the minimum required for oxygen supply for biodegradation. During air injection, the air will be monitored for volatile hydrocarbons at the soil surface and in the breathing zone to account for any volatilization that does occur and to ensure safe working conditions.

#### 3.6 Blower System

A 1-horsepower regenerative blower capable of injecting air at a flow rate of 20 to 40 scfm at a pressure of 56 inches of water will be used to conduct the initial air permeability test at these sites. Air injection will be used to provide oxygen to soil bacteria and to minimize emissions of volatiles to the atmosphere. If initial testing indicates that less flow is required to supply oxygen throughout the test volume, the blower output will be reduced for the extended testing via an air bleed valve. Figure 3.5 is a schematic of a typical air injection system that will be used for pilot testing at this site. The maximum power requirement anticipated for this pilot test is either 230-volt, single-phase, 30-amp service or 120-volt 30 amp service. Additional details on power supply requirements are described in Section 5.0, Base Support Requirements.

#### 3.7 In Situ Respiration Test

The objective of the *in situ* respiration test is to determine the rate at which soil bacteria degrade petroleum hydrocarbons. Respiration tests will be performed at the three VMPs at each site. Air will be injected into each VMP for a 20 to 24-hour

# LEGEND


- INLET AIR FILTER
- VACUUM GAUGE (in H2O)
- BLOWER GAST/70 SCFM @ 20 INCHES 1/2 O REGENERATIVE W/1HP DRIVE MOTOR  $\odot$
- MANUAL PRESSURE RELIEF (BLEED) VALVE 1 1/2" GATE (4)
- AUTOMATIC PRESSURE RELIEF VALVE (6)
- PRESSURE GAUGE (in H2O) 6
  - TEMPERATURE GAUGE ('F)
- BREAKER BOX (115V/SINGLE PHASE/30 AMP) POWER SWITCH ® (e)
- (10) AIR VELOCITY MEASURE PORT

# DRAWING IS NOT TO SCALE

# PROPOSED BLOWER SYSTEM FOR AIR INJECTION

# CAPE CANAVERAL, FLORIDA

S S S ENGINEERING—SCIENCE, Orlando, Florida



air injection period, which will be used to oxygenate local contaminated soil. At the end of the air injection period, the air supply will be cut off, and oxygen and carbon dioxide levels will be monitored until the oxygen level falls below 5% or for five days whichever is earlier. The decline in oxygen and increase in carbon dioxide concentrations over time will be used to estimate rates of bacterial degradation of fuel residuals. Helium will also be injected at all three points at each site to ensure that the VMPs do not leak and to estimate oxygen diffusion rates in site soils.

#### 3.8 Air Permeability Test

The objective of the air permeability test is to determine the extent of the subsurface that can be oxygenated using the VWs. Air will be injected into the 4-inch diameter VW using the blower unit, and pressure response will be measured at each VMP with differential pressure gauges to determine the region influenced by the unit. Oxygen will also be monitored in the VMPs to ascertain that oxygen levels in the soil increase as the result of air injection. One air permeability test lasting 4 to 8 hours will be performed.

#### 3.9 Installation of Extended Pilot Test Bioventing System

Extended, 1-year bioventing pilot systems will also be installed at Facilities 1748, 44625D, and 44625E. At each site an electrical contractor will provide a power pole with either 230-volt, single-phase, 30-amp breaker box or 120-volt 30 amp breaker box. Two 120-volt utility receptacles will also be provided. The blower will be housed in a small, prefabricated shed to provide protection from the weather.

The system will be in operation for 1 year, and at 6 months and 12-months of operation, ES personnel will conduct in situ respiration tests to monitor the long-term performance of this bioventing system. Weekly system checks will be performed by either Patrick AFB or Cape Canaveral AFS personnel. If required, major maintenance of the blower unit may be performed by ES personnel. Detailed blower system information and a maintenance schedule will be included in the operation and maintenance (O&M) manual provided to the base. More detailed information regarding the test procedures can be found in the protocol document.

#### 4.0 EXCEPTIONS TO PROTOCOL PROCEDURES

The testing procedures that will be used to measure the air permeability of the soil and *in situ* respiration rates are described in Sections 4 and 5 of the protocol document. The only foreseen exception to field testing protocol procedures is the collection of the soil samples.

Soil borings for VMP installations will be advanced using a hand auger at these sites. A drilling contractor will not be needed for this procedure and the typical borehole diameter for each monitoring point will be approximately 4 inches, as illustrated in Figure 3.4.

#### 5.0 BASE SUPPORT REQUIREMENTS

#### 5.1 Test Preparation

The following base support is needed prior to the arrival of an excavation contractor and the ES test team:

- Assistance in obtaining a digging permit at Facilities 1748, 44625D, and 44625E at Cape Canaveral AFS.
- Base will approve location of power supply to be installed by the electrical contractor.
- Provide any paperwork required to obtain gate passes and security badges for approximately four (4) ES employees and two drilling contractors. Vehicle passes will be needed for three trucks.

During the initial 3-week pilot test, the following base support is needed:

- Twelve square feet of desk space and a telephone in a building located as close to the site as practical.
- A decontamination pad where the drilling contractor can clean equipment.
- Acceptance of responsibility by Patrick AFB and Cape Canaveral AFS for soil cuttings from VW and VMP borings, including any drum sampling to determine hazardous waste status.
- The use of a fax machine for transmitting 15 to 20 pages of test results.

During the 1-year extended pilot test at these facilities, the following support is needed:

- Check the blower system at the site once a week to ensure that it is operating and to record the air injection pressure. ES will provide a brief training session and an O&M checklist for this procedure.
- Notify Mr. Steve Archabal, ES-Orlando, (407) 841-8114; Mr. Dave Brown, ES-Syracuse, (315) 451-9560; or Mr. Marty Faile, AFCEE, (210) 536-4342, if the blower or motor stop operating.

■ Arrange site access for an ES technician to conduct *in situ* respiration tests approximately 6 months and 1 year after the initial pilot test.

#### 6.0 PROJECT SCHEDULE

The following schedule is contingent upon timely approval of this pilot test work plan:

Event	Date
Draft Test Work Plan to AFCEE/Patrick AFB/Cape Canaveral AFS	11/22/93
Begin Pilot Test	11/29/93
Complete Initial Pilot Test	12/23/93
Interim Results Report	February 94
Second Respiration Test	June 94
Final Respiration Test	December 94

After a period of 1 year, a decision will be made by AFCEE, Patrick AFB, and Cape Canaveral AFS to either remove the pilot system or to expand the system for full-scale remediation of the site soils.

#### 7.0 POINTS OF CONTACT

Mr. Hugh Houghton 45 CES/DEEV Patrick AFB, FL 32925 (407) 494-4721

Lt. Colonel Ross Miller/Mr. Marty Faile AFCEE/EST Brooks AFB, Texas 78235-5000 (210) 536-4331/(210) 536-4342

Dave Brown
Engineering-Science, Inc.
290 Elwood Davis Road
Liverpool, New York
(315) 451-9560

Steve Archabal Engineering-Science, Inc. 255 S. Orange Avenue, Suite 1201 Orlando, FL 32801 (407) 841-8114

#### 8.0 REFERENCES

- CH<sub>2</sub>M Hill, 1992. Hazwrap, Martin Marietta Phase I Contamination Assessment, Cape Canaveral Air Force Station, Orlando, Florida. April/July.
- Engineering-Science, Inc. 1993. Project Management Plan for AFCEE Bioventing, Appendix D, Field Sampling Plan. Denver, Colorado. January.
- Hinchee, R.E., Ong, S.K., Miller, R.N., Downey, D.C., Frandt, R. 1992. Test Plan and Technical Protocol for a Field Treatability Test for Bioventing. Columbus, Ohio. January.

#### PART II

## DRAFT INTERIM PILOT TEST RESULTS REPORT FOR FACILITIES 1748, 44625D, AND 44625E

#### CAPE CANAVERAL AFS, FLORIDA

**April 1994** 

Prepared for:

Air Force Center for Environmental Excellence Brooks AFB, Texas

and

45 CES/CEV

Patrick AFB, Florida

Prepared by:

Engineering-Science, Inc. 1700 Broadway, Suite 900 Denver, Colorado 80290

#### CONTENTS

## PART II - DRAFT INTERIM PILOT TEST RESULTS REPORT FOR FACILITIES 1748, 44625D AND 44625E CAPE CANAVERAL AFS, FLORIDA

			<u>Page</u>
1.0	Facil	lity 1748	П-1
	1.1	Pilot Test Design and Construction	
		1.1.1 Air Injection Vent Well Construction	11-2
		1.1.2 Permanent Monitoring Points	II-2
		1.1.3 Blower Unit Installation and Operation	11-6
	1.2	Soil and Soil Gas Sampling Results	
	1.3	Exceptions to Test Protocol Document Procedures	11-9
	1.4	Field OA/OC Results	11-9
	1.5	Pilot Test Results	9
		1.5.1 Initial Soil Gas Chemistry	9
		1.5.2 Air Permeability	9
		1.5.3 Oxygen Influence	9
		1.5.4 In Situ Respiration Rates	11-13
		1.5.5 Potential For Air Emissions	II-13
			TT 10
2.0	Facil	lity 44625D, Cape Canaveral AFS	11-19
	2.1	Pilot Test Design and Construction	11-19
		2.1.1 Air Injection Vent Well Construction	II-19
		2.1.2 Permanent Monitoring Points	п-19
		2.1.3 Blower Unit Installation and Operation	ш-23
	2.2	Soil and Soil Gas Sampling Results	п-23
	2.3	Exceptions to Test Protocol Document Procedures	
	2.4	Field QA/QC Results	TI 26
	2.5	Pilot Test Results	11-20
		2.5.1 Initial Soil Gas Chemistry	11 26
		2.5.2 Air Permeability	II 26
		2.5.3 Oxygen Influence	п 20
		2.5.4 In Situ Respiration Rates	11-30
		2.5.5 Potential For Air Emissions	11-30
3.0	Essi	Hity MACOSE Cong Congyard AEC	II-36
3.0	3.1	ility 44625E, Cape Canaveral AFSPilot Test Design and Construction	П-36
	5.1	3.1.1 Air Injection Vent Well Construction	П-36
		3.1.2 Permanent Monitoring Points	П-36
		3.1.3 Blower Unit Installation and Operation	Π-40
	2.2		11-40
	3.2	Exceptions to Test Protocol Document Procedures	11-43
	3.3	Field QA/QC Results	11-43
	3.4	Pilot Test Results	11-43
	3.5		 11_43
		3.5.1 Initial Soil Gas Chemistry	11_43
		3.5.2 Air Permeability	
		3.5.3 Oxygen Influence	
		3.5.4 In Situ Respiration Rates	
		3.5.5 Potential Air Emissions	XI-4 /

#### **CONTENTS (Continued)**

4.0	Recommendations	II-53
5.0	References	II-53
	TABLES	
No.	<u>Title</u>	Page
	Facility 1748, Cape Canaveral AFS	
1.1 1.2 1.3 1.4	Soil and Soil Gas Analytical Results Initial Soil Gas Chemistry Pressure Response During Air Permeability Test Influence of Air Injection at Vent Well on Monitoring Point Oxygen Levels Oxygen Utilization Rates	II-11 II-12 II-14
	Facility 44625D, Cape Canaveral AFS	
2.1 2.2 2.3 2.4 2.5	Soil and Soil Gas Analytical Results Initial Soil Gas Chemistry Pressure Response During Air Permeability Test Influence of Air Injection at Vent Well on Monitoring Point Oxygen Levels Oxygen Utilization Rates	П-28 П-29 П-31
	Facility 44625E, Cape Canaveral AFS	
3.1 3.2 3.3 3.4 3.5	Soil and Soil Gas Analytical Results Initial Soil Gas Chemistry Pressure Response During Air Permeability Test Influence of Air Injection at Vent Well on Monitoring Point Oxygen Levels Oxygen Utilization Rates	II-45 II-46 II-48
	FIGURES	
No.	<u>Title</u>	<u>Page</u>
	Facility 1748, Cape Canaveral AFS	
1.1 1.2 1.3 1.4 1.5 1.6 1.7	As-Built Vent Well, Monitoring Point, and Blower Locations Hydrogeologic Cross Section As-Built Vent Well Construction Detail As-Built Monitoring Point Construction Detail As-Built Blower System for Air Injection Respiration Test - Oxygen and Helium Concentrations, MPA-5.5 Respiration Test - Oxygen and Helium Concentrations, MPB-5.5 Respiration Test - Oxygen and Helium Concentrations, MPC-5.5	П-4 П-5 П-7 П-8 П-16 П-17

#### **CONTENTS (Continued)**

#### FIGURES (Continued)

<u>No.</u>	<u>Title</u>	Page
	Facility 44625D, Cape Canaveral AFS	
2.1 2.2 2.3 2.4 2.5 2.6 2.7 2.8	As-Built Vent Well, Monitoring Point, and Blower Locations Hydrogeologic Cross Section As-Built Vent Well Construction Detail As-Built Monitoring Point Construction Detail As-Built Blower System for Air Injection. Respiration Test - Oxygen and Helium Concentrations, MPA-5.5 Respiration Test - Oxygen and Helium Concentrations, MPB-5.5 Respiration Test - Oxygen and Helium Concentrations, MPC-5.5	. П-21 . П-22 . П-24 . П-25 . П-32 . П-33
	Facility 44625E, Cape Canaveral AFS	
3.1 3.2 3.3 3.4 3.5 3.6 3.7 3.8	As-Built Vent Well, Vapor Monitoring Point, and Blower Locations	. II-38 . II-39 . II-41 . II-42 . II-49
Appe	endix A - System Maintenance Instructions endix B - Geologic Boring Logs, Test Data, and Calculations endix C - Chain of Custody Forms	

#### **PART II**

# DRAFT INTERIM PILOT TEST RESULTS REPORT FOR FACILITIES 1748, 44625D, AND 44625E CAPE CANAVERAL AFS, FLORIDA

An initial bioventing pilot test was performed by Engineering-Science, Inc. (ES) at each of the following sites at Cape Canaveral Air Force Station (AFS), Florida: Facility 1748, Facility 44625D, and Facility 44625E from December 30, 1993 through February 8, 1994. The three primary objectives of the pilot tests are:

- To assess the potential for supplying oxygen throughout the contaminated soil interval;
- To determine the rate at which indigenous microorganisms will degrade fuel when supplied with oxygen-rich soil gas, and
- To evaluate the potential for sustaining these rates of biodegradation until fuel contamination is remediated to concentrations below regulatory standards.

The purpose of this report is to describe the results of the initial pilot tests and to make specific recommendations for extended testing to determine the long-term impact of bioventing to remediate the site contaminants. Descriptions of the history, geology, and site contaminants of each site are found in Part I of this report, Bioventing Pilot Test Work Plan.

#### 1.0 FACILITY 1748

#### 1.1 Pilot Test Design and Construction

The following sections describe the final design and installation of the bioventing system at Facility 1748, the base cafeteria. A vertical air injection venting well (VW) was installed on December 23, 1993, by Engineering-Science, Inc. (ES) of Orlando, Florida and a subcontractor, Groundwater Protection, Inc. (Drilling Division) of Orlando, Florida. Four permanent pressure/vapor monitoring points (MPs) were installed on December 30, 1993. The VW construction, MP installations, and soil sampling were directed by Mr. Steve Archabal, the ES site manager. The following sections describe in more detail the final design, installation, and testing of the bioventing system at this site.

One VW, four permanent MPs, and a blower unit in a weatherproof enclosure were installed at Facility 1748. A single-depth MP construction was used at the site, the only exception being the background MP location. A monitoring depth screen interval of 5.0 to 5.5 feet below land surface (bls) was installed at all single-depth MP

locations, due to the shallow water table at approximately 6.5 feet bls at this site. At the background MP location, a multi-depth construction was used, with the screened intervals installed at 2.5 to 3.0 and 5.0-5.5 feet bls. Figure 1.1 depicts the test area with the locations of the MPs, VW, and blower at Facility 1748. Figure 1.2 shows a hydrogeologic cross section oriented in a north-south direction.

#### 1.1.1 Air Injection Venting Well Construction

The VW was installed within the area of the former underground 4,000-gallon diesel fuel tank, as shown in Figure 1.1. The VW was constructed in visibly contaminated, oxygen-depleted soils. Soils encountered during the VW construction were darkly stained and emitted hydrocarbon odors.

The installation of the VW was in accordance with typical Air Force Center for Environmental Excellence (AFCEE) work plan protocols (Hinchee et al., 1992). On the date of the VW installation, groundwater level at the Facility 1748 was approximately 6.5 feet bls.


The VW was constructed using 4-inch-diameter, Schedule 40 polyvinyl chloride (PVC) casing with 5 feet of 0.03-inch slotted PVC screen installed from 3 to 8 feet bls. The annular space between the well casing and borehole was filled with 6/20 graded silica sand to approximately 1 foot above the well screen. A 1-foot layer of bentonite pellets was placed above the sand and hydrated in place. A 1-foot cement grout seal was placed over the bentonite to ground surface. The top of the VW was completed with a flush-mount steel well manhole set in a 2x2-foot concrete pad. Figure 1.3 shows the as-built construction details for the VW. The geologic soil boring log for the VW installation is presented in Appendix B.


#### 1.1.2 Permanent Monitoring Points

Four permanent, single-depth MPs were installed at Facility 1748 on December 30, 1993. MPs CA2-MPA, CA2-MPB, and CA2-MPC were installed at respective distances of 10, 20, and 30 feet from the VW location. A permanent background MP, MPBG, was installed 72 feet south and 19 feet due east of the VW location (see Figure 1.1). All permanent MP boreholes were advanced using a decontaminated stainless steel hand auger. MPA, MPB, and MPC were screened at 5.0 to 5.5 feet bls, and the multi-depth MPBG was screened at 2.5 to 3.0 and 5.0 to 5.5 feet bls.

All four permanent MPs were constructed using 0.5-inch-diameter PVC screens and casing installed in 4-inch-diameter boreholes. Each MP was constructed using a 6-inch section of 0.02-inch-slotted, Schedule 40 PVC screen and Schedule 80 PVC casing. Each screened interval was surrounded by a filter pack of 6/20 graded coarse silica sand.

Thermocouples were also installed at the screened intervals of MPA, MPC, and MPBG. Bentonite pellets, hydrated in place, were used to seal the annulus around each MP riser above the sand pack and between the screened intervals at the background MP location. Then a 3-foot-thick grout seal was placed over the bentonite to ground surface. The top of each MP PVC riser was completed at ground surface with a brass ball valve and a 0.25-inch brass hose barb. Each MP was completed at the surface with an 8-inch flush-mounted steel manhole set in a concrete 2x2-foot pad. The lid to





94DN0345, 04/05/94 at 10:52

the manhole was set approximately 1 inch above ground surface, and the concrete base was sloped toward the edges to promote drainage of surface water away from the MP. Figure 1.4 shows a typical permanent MP construction detail.

# 1.1.3 Blower Unit Installation and Operation

A 1-horsepower Gast® regenerative blower unit was installed at Facility 1748 for the initial and extended pilot tests. The Gast® blower was installed in a weatherproof enclosure and electrically wired for 115-volt, 30-amp power.

Air is supplied by the blower through a 1.5-inch-diameter above/below ground steel header pipe that is attached to the VW. Figure 1.5 shows the configuration, instrumentation, and specifications for the blower and air injection system.

Prior to departing from the site, ES personnel provided operations and maintenance (O&M) instructions to AFS personnel. A copy of the O&M instructions is provided in Appendix A.


# 1.2 SOIL AND SOIL GAS SAMPLING RESULTS

Soils at Facility 1748 consist of loose, fine- to coarse-grained sand, with shell fragments. This soil profile was consistent across the site at each boring location from ground surface to below the water table surface, which typically averages 6 to 8 feet bls. The fine to coarse sands range in color from light gray to gray, with the exception being a layer of brown sand from 3.5 to 4.5 feet bls.

Soil hydrocarbon contamination at this site appeared to be confined mainly within the boundaries of the former 4,000-gallon diesel underground storage tank (UST) location. Contaminated soils were identified based on visual appearance, odor, and volatile organic compound (VOC) field screening results. Heavily contaminated soils were encountered during the VW installation and during all MP installations. Soils were not contaminated at the background MP location (MPBG). Contaminated soils exhibited strong hydrocarbon odors and were visibly stained. The highest concentrations of total VOCs occurred at depths below 4 feet. Soil gas VOC readings ranged from 140 to >20,000 parts per million, volume per volume (ppmv) of total hydrocarbons at the MPs and VW locations.

Soil samples for laboratory analysis were collected from the stainless steel handauger bucket during the installation of the permanent MPs. Soil samples were collected from 5.5 feet bls at MPA, MPB, and the VW boreholes. Soil samples were screened for VOCs using a GasTech/Trace-techtor® hydrocarbon analyzer to determine the presence of contamination and to select soil samples for laboratory analysis.

Soil samples were shipped via Federal Express® to Pace, Inc. in Huntington Beach, California for chemical and physical analyses. Each of the soil samples was analyzed for the following parameters: total recoverable petroleum hydrocarbons (TRPH); benzene, toluene, ethylbenzene, and xylenes (BTEX); iron; alkalinity; total Kjeldahl nitrogen (TKN); pH; phosphates; percent moisture; and grain size distribution. Soil gas samples were shipped via Federal Express® to Air Toxics, Inc. in Folsom,



# MONITORING POINT CONSTRUCTION SPECIFICATIONS

Monitoring <u>Point No.</u>	Borehole Depth (FT)	Screen Interval (Feet BLS)
MPA-5.5	5.5	5.0-5.5
MPB-5.5	5.5	5.0-5.5
MPC-5.5	5.5	5.0-5.5
BACKGROUND	MONITORING POINT	
MP-3.0 MP-5.5	5.5	2.5-3.0 5.0-5.5
NOTE.		

NOTE:

AS-BUILT BACKGROUND MP WAS CONSTRUCTED THE SAME AS MP'S AT FACILITY 44625D/E.

DRAWING IS NOT TO SCALE

AS-BUILT PERMANENT
MONITORING POINT CONSTRUCTION DETAIL
FACILITY 1748

CAPE CANAVERAL AFS, FLORIDA

ENGINEERING-SCIENCE, INC. Denver, Colorado



# LEGEND

- ) INLET AIR FILTER
- (2) VACUUM GAUGE (in H<sub>2</sub>O)
- (3) BLOWER GAST/70 SCFM @ 20 INCHES H20 REGENERATIVE W/1HP DRIVE MOTOR

(3) BLOWER

(₫-

) AIR FILTER

(2)

FROM ATMOSPHERE

- (4) AUTOMATIC PRESSURE RELIEF VALVE
- (5) MANUAL PRESSURE RELIEF (BLEED) VALVE 1 1/2" GATE
- 6 IN-LINE 1 1/2 GATE VALVE
- 7) PRESSURE GAUGE (in H2O)
- (B) TEMPERATURE GAUGE (F)
- 9 POWER SWITCH/TIMEP BOX

VENT WELL (INJECTION)

9

**6** 

- (10) BREAKER BOX (115V/SINGLE PHASE/30 AMP)
- (11) AIR VELOCITY MEASURE PORT

DRAWING IS NOT TO SCALE

# AS-BUILT BLOWER SYSTEM FOR AIR INJECTION

CAPE CANAVERAL AFS,, FLORIDA

ENGINEERING—SCIENCE, INC. Denver, Colorado

California for total volatile hydrocarbon (TVH) and BTEX analyses. The results of these analyses are presented in Table 1.1, and the chain-of-custody form is presented in Appendix C.

# 1.3 EXCEPTIONS TO TEST PROTOCOL DOCUMENT PROCEDURES

Test procedures described in the protocol document (Hinchee et al., 1992) were used to complete the treatability pilot tests at this site. No exceptions to the standard protocol document or the Bioventing Pilot Test Work Plan (Part I) were necessary at Facility 1748.

# 1.4 FIELD QA/QC RESULTS

Field quality assurance/quality control (QA/QC) samples were not collected or required at this site.

## 1.5 PILOT TEST RESULTS

# 1.5.1 Initial Soil Gas Chemistry

Prior to initiating any air injection, all MPs were purged until oxygen levels had stabilized, and initial oxygen, carbon dioxide, and TVH concentrations were sampled using portable gas analyzers, as described in the technical protocol document (Hinchee et al., 1992). In soils surrounding each MP screened interval and at the VW, microorganisms had completely depleted soil gas oxygen supplies, indicating significant biological activity and soil contamination. The uniformity of zero oxygen levels at this site is primarily the result of the vertical and horizontal uniformity of soil bioactivity and contamination. Table 1.2 describes initial soil gas chemistry at this site. The background MP located at this site showed near-atmospheric levels of oxygen and carbon dioxide, indicating that uncontaminated soils at the same depth do not exert significant oxygen demand due to natural organic biodegradation or abiotic reactions.

# 1.5.2 Air Permeability

An air permeability test was conducted according to protocol document procedures. Air was injected into the VW for 4 hours at a rate of approximately 58 standard cubic feet per minute (scfm) and an average pressure of 25 inches of water. Steady-state pressure levels were achieved in all MPs after only 5 minutes of air injection. Table 1.3 provides the steady-state pressures at each MP. Due to this rapid pressure response, the steady-state method of determining air permeability was selected. A soil gas permeability value of 60 darcys, typical for sandy soils, was calculated for this site. A radius of pressure influence of over 30 feet was observed.

# 1.5.3 Oxygen Influence

The radius of oxygen increase in the subsurface resulting from air injection into the VW during pilot testing is an important design parameter for full-scale bioventing systems. Optimization of full-scale and multiple vent well systems requires pilot testing to determine the volume of soil that can be oxygenated at a given flow rate and vent well screen configuration.

TABLE 1.1
SOIL AND SOIL GAS LABORATORY ANALYTICAL RESULTS
FACILITY 1748

Analyte (Units) <sup>a</sup> /	Sample Location-Depth (feet below land surface)			
Soil Gas Hydrosarbons	<u>VW 3-6.5</u>	MPA-5.5	MPC-5.5	
Soil Gas Hydrocarbons FVH (ppmv)	510	740	1,000	
Benzene (ppmv)	0.26	0.91	3.3	
Toluene (ppmv)	NDb/	ND	ND	
Ethylbenzene (ppmv)	1.2	3.6	5.5	
Xylenes (ppmv)	2.6	3.9	3.4	
Call III.dan and an	<u>VW-5.5</u>	MPA-5.5	MPB-5.5	
<u>Soil Hydrocarbons</u> TRPH (mg/kg)	18,800	20,200	12,600	
Benzene (mg/kg)	ND	20,200 ND	ND	
Toluene (mg/kg)	ND	ND	ND	
Ethylbenzene (mg/kg)	0.51	5.1	ND	
Xylenes (mg/kg)	3.7	8.3	5.1	
Soil Inorganics				
Iron (mg/kg)	916	712	1,080	
Alkalinity (mg/kg as CaCO <sub>3</sub> )	360	282	543	
pH (units)	7.8	8.8	8.8	
TKN (mg/kg)	66	100	170	
Phosphates (mg/kg)	190	230	510	
Soil Physical Parameters				
Soil Temperature (°F) <sup>d/</sup>	NS <sup>c/</sup>	72.8	NS	
Moisture (% wt.)	9.1	11.8	6.7	
Gravel (%)	0.2	0.1	0.0	
Sand (%)	96.6	96.9	96.2	
Silt (%)	0.6	0.4	1.1	
Clay (%)	2.6	2.6	2.6	

a/ TRPH = total recoverable petroleum hydrocarbons; TPH = total petroleum hydrocarbons; mg/kg = milligrams per kilogram, ppmv = parts per million, volume per volume; CaCO<sub>3</sub> = calcium carbonate; TKN = total Kjeldahl nitrogen.

b/ ND = not detected.

c/ NS = not sampled.

d/ Soil temperature at MPC-5.5 was 74.6°F.

TABLE 1.2
INITIAL SOIL GAS CHEMISTRY
FACILITY 1748
CAPE CANAVERAL AFS, FLORIDA

Sample Location	Depth (ft)	O <sub>2</sub> (%)	CO <sub>2</sub> (%)	Field TVH (ppmv) <sup>a/</sup>	Lab TVH (ppmv) <sup>b/</sup>	Lab TRPH (mg/kg) <sup>c/</sup>
MPA	5.5	0.0	16.9	360	740	20,200
MPB	5.5	0.0	17.5	420	NC c/	12,600
MPC	5.5	0.0	18.0	500	1,000	NS c/
vw	3-6.5	0.0	16.5	300	510	18,800
MPBG	3.0	20.5	0.5	0.0	NS	NS
	5.5	20.3	0.7	0.0	NS	NS

a/ Gastech/Trace-techtor® field screening results.

b/ Laboratory results.

c/ NS = not sampled.

# TABLE 1.3 MAXIMUM PRESSURE RESPONSE AIR PERMEABILITY TEST

# **FACILITY 1748**

	Distance from injection well (VW) (feet)			
· ·	10 (MPA)	20 (MPB)	30 (MPC)	
Depth (feet bls)	5.5	5.5	5.5	
Time (min)	10.0	10.0	10.0	
Max Press (inches H <sub>2</sub> 0)	2.3	0.97	0.44	

Table 1.4 presents the change in soil gas oxygen levels that occurred during 4 hours of air injection. This period of air injection at approximately 58 scfm produced changes in soil gas oxygen levels throughout the 30-foot radius of the pilot testing area. Based on this rapid increase in oxygen levels, it is anticipated that the radius of influence for a long-term bioventing system at this site will exceed 30 feet. During the startup of the extended pilot test system, the air injection rate will be reduced to the minimum flow required to provide oxygen within a radius of 30 feet from the VW. Based on similar systems constructed in sandy soils, it is anticipated that an air injection rate of approximately 20 scfm will be sufficient for extended testing.

# 1.5.4 In Situ Respiration Rates

The *in situ* respiration test was performed by injecting a mixture of air (oxygen) and approximately 4 to 5 percent helium (inert tracer gas) into the three MP screened intervals (MPA-5.5, MPB-5.5, and MPC-5.5) for a 20-hour period. Oxygen loss and other changes in soil gas composition over time were then measured at each MP. Oxygen, TVH, carbon dioxide, and helium were measured for a period of approximately 16 hours following air injection. The measured oxygen losses were then used to calculate biological oxygen utilization rates. The results of *in situ* respiration testing for MPA, MPB, and MPC are presented in Figures 1.6 through 1.8. Table 1.5 provides a summary of the oxygen utilization rates.

Because helium is a conservative, inert gas, the change in helium concentrations over time can be useful in determining the effectiveness of the bentonite seals above MP screened intervals. Figures 1.6 through 1.8 compare oxygen utilization and helium retention. Because helium will diffuse approximately three times faster than oxygen due to oxygen's greater molecular weight, the measured oxygen loss at these MPs is the result of bacterial respiration and not due to oxygen diffusion or oxygen loss from leaks in the MPs.

Oxygen loss occurred at moderate rates, ranging from 0.0024 percent per minute (%/min) at MPB-5.5 to 0.0027 %/min at MPA-5.5. Based on test results at MPA-5.5, an estimated 640 milligrams (mg) of fuel per kilogram (kg) of soil can be degraded each year at this site. This estimate is based on an air-filled porosity of approximately 0.12 liter per kg of soil, and a conservative ratio of 3.5 mg of oxygen consumed for every 1 mg of fuel biodegraded. This estimate is conservative because moisture content at MPA-5.5 was greater than at the other MP locations, resulting in a lower air-filled porosity and rate of fuel biodegradation. Additional information on the calculations for fuel biodegradation can be found in Section 5 of the protocol document. Actual rates will vary, and could be reduced during the rainy season due to higher soil moisture and reduced air-filled porosity, or increased during warm summer months.

### 1.5.5 Potential For Air Emissions

The long-term potential for air emissions from full-scale bioventing operations at this site is considered low because the site is partially paved and of the low initial BTEX levels (<10 ppmv) in the site soil gas and the low injection rate proposed for extended testing. Health and safety monitoring was conducted during the 4-hour air permeability test using a GasTech® total hydrocarbon analyzer sensitive to 1-ppmv

**TABLE 1.4** 

# INFLUENCE OF AIR INJECTION AT VENT WELL

# ON MONITORING POINT OXYGEN LEVELS

# **FACILITY 1748**

MP	Distance From VW (ft)	Depth (ft bls)	Initial O <sub>2</sub> (%)	Final O <sub>2</sub> (%) Permeability Test <sup>a</sup> /
A	10	5.5	0.0	NSb/
В	20	5.5	0.0	NS
C	30	5.5	0.0	13.7

a/ Reading taken at end of 4 hours of air injection.

b/ NS = Not sampled.

# **TABLE 1.5**

# **OXYGEN UTILIZATION RATES**

# **FACILITY 1748**

Location	O2 Loss <sup>a</sup> / (%)	Test <sup>b/</sup> Duration (min)	O2 Utilization <sup>c/</sup> Rate (%/min)
MPA-5.5	17.9	6,960	0.0027
MPB-5.5	16.4	6,960	0.0024
MPC-5.5	18.7	6,960	0.0027

a/ Actual measured oxygen loss.

b/ Elapsed time from beginning of test to time when minimum oxygen concentration was measured.

c/ Values based on best-fit lines (Figures 1.6 through 1.8).

(oxygen utilization rate) k= 0.002721 %/min. Percent Oxygen Percent Helium 4.5 2.5 4.0 3.5 3.0 2.0 0. 0.5 - 0.0 7.00 6.00 5.00 Time (minutes x 1000) 4.00 3.00 2.00 1.00 0.00 20.0 \*\* 18.0 16.0 14.0 12.0 10.0 8.0 6.0 0.0 4.0 2.0 Percent Oxygen

Facility 1748 (Base Cafeteria), MPA-5.5

Cape Canaveral AFS, FL

Oxygen and Helium Concentrations

(oxygen utilization rate) k= 0.002453 %/min. Percent Oxygen Percent Helium 4.5 2.5 4.0 3.5 3.0 2.0 1.5 1.0 0.5 - 0.0 7.00 6.00 5.00 Time (minutes x 1000) 4.00 3.00 2.00 1.00 0.00 + 0.0 20.0 18.0 16.0 8.0 2.0 14.0 12.0 10.0 6.0 4.0 Percent Oxygen

Facility 1748 (Base Cafeteria), MPB-5.5

Cape Canaveral AFS, FL

Oxygen and Helium Concentrations

(oxygen utilization rate) k= 0.002746 %/min. Percent Oxygen Percent Helium 4.5 4.0 3.5 3.0 2.5 2.0 1.5 + 0.0 0.5 7.00 6.00 5.00 Time (minutes x 1000) 4.00 3.00 2.00 1.00 0.00 0.0 20.0 18.0 16.0 14.0 12.0 8.0 0.9 2.0 10.0 4.0 Percent Oxygen

Facility 1748 (Base Cafeteria), MPC-5.5

Cape Canaveral AFS, FL

Oxygen and Helium Concentrations

increases in volatile hydrocarbons. No sustained emissions in excess of 1 ppmv were detected in the breathing zone. Because the potential for air emissions is highest during the initial few hours of air injection, the long-term emission potential is considered low.

### 2.0 FACILITY 44625D

# 2.1 Pilot Test Design and Construction

The following sections describe the final design and installation of the bioventing system at Facility 44625D, the generator shop drum storage area. One air injection VW was installed on December 23, 1993, by ES and a subcontractor, Groundwater Protection, Inc. (Drilling Division), both of Orlando, Florida. Three permanent pressure/vapor MPs were installed on December 30, 1993. The VW construction, MP installations, and soil sampling were directed by Mr. Steve Archabal, the ES site manager. The following sections describe in more detail the final design, installation, and testing of the bioventing system at this site.

One VW, three permanent MPs, and a blower unit in a weatherproof enclosure were installed at Facility 44625D. The locations of the MPs and VW followed the original work plan (Part I of this report). A multi-depth MP construction was used at the site. Monitoring depth screen intervals of 2.5 to 3.0 and 5.0 to 5.5 feet bls were installed at this site. Figure 2.1 depicts the test area with the locations of the MPs, VW, and blower at Facility 44625D. Figure 2.2 shows a hydrogeologic cross section oriented in an east-west direction.

# 2.1.1 Air Injection Venting Well Construction


The VW was installed near the drum storage area of the generator maintenance area, as shown in Figure 2.1. The VW was constructed in visibly contaminated, oxygen-depleted soils. Soils encountered during the VW construction were darkly stained and emitted strong hydrocarbon odors.


The installation of the VW was in accordance with typical AFCEE work plan protocol (Hinchee et al., 1992). On the date of the VW installation, water level at Facility 44625D was approximately 6.5 feet bls.

The VW was constructed using 4-inch-diameter, Schedule 40 PVC casing with 5 feet of 0.03-inch slotted PVC screen installed from 3 to 8 feet bls. The annular space between the well casing and borehole was filled with 6/20 graded silica sand to approximately 1 foot above the well screen. A 1-foot layer of bentonite pellets were placed above the sand and hydrated in place. A 1-foot cement grout seal was placed over the bentonite to ground surface. The top of each VW was completed with a flushmount steel well manhole set in a 2x2-foot concrete pad. Figure 2.3 shows the as-built construction details for the VW. The geologic soil boring log for the VW installations is provided in Appendix B.

# 2.1.2 Permanent Monitoring Points

Three permanent, multi-depth MPs were installed at Facility 44625D on December 30, 1993. MPs CA3-MPA, CA3-MPB, and CA3-MPC were installed at respective distances of 10, 20, and 30 feet from the VW location. A permanent background MP,





94DN0358, 04/05/94 ot 10:54

MPBG, was installed at Facility 1748 in similar soil conditions (see Figure 1.1). All permanent MP boreholes were advanced using a decontaminated stainless steel hand auger. MPA, MPB, and MPC each were screened at 2.5-3.0 and 5.0-5.5 feet bls.

All three permanent MPs were constructed using 0.5-inch-diameter PVC screens and casing installed in 4-inch-diameter boreholes. Each MP was constructed using a 6-inch section of 0.02-inch slotted, Schedule 40 PVC screen and Schedule 80 PVC casing. The screened interval was surrounded by a filter pack of 6/20 graded coarse silica sand.

Thermocouples were also installed at the screened intervals of MPA and MPC. Bentonite pellets, hydrated in place, were used to seal the annulus around each MP riser above the gravel pack and between the screened intervals. Then a 1-foot grout seal was placed over the bentonite to ground surface. The top of each MP PVC riser was completed at ground surface with a brass ball valve and a 0.25-inch brass hose barb. Each MP was completed at the surface with a 8-inch flush-mounted steel manhole set in a concrete 2x2-foot pad. The lid to the manhole was set approximately 1 inch above ground surface, and the concrete base was sloped toward the edges to promote drainage of surface water away from the MP. Figure 2.4 shows a typical permanent MP construction detail.

# 2.1.3 Blower Unit Installation and Operation

A 1-horsepower Gast® regenerative blower unit was installed at Facility 44625D for the initial and extended pilot tests. The Gast® blower was installed in a weatherproof enclosure and electrically wired for 115 volt, 30-amp power.

Air is supplied by the blower through a 1.5-inch-diameter above/below ground steel header pipe that is attached to the VW. Figure 2.5 shows the configuration, instrumentation, and specifications for the blower and air injection system.


Prior to departing from the site, ES personnel provided O&M instructions to AFS personnel. A copy of these instructions is provided in Appendix A.

# 2.2 SOIL AND SOIL GAS SAMPLING RESULTS

Soils at Facility 44625D consist of loose, fine- to coarse-grained sand, with shell fragments. This soil profile was consistent across the site at each boring location from ground surface to below the water table surface, which typically averages 6 to 8 feet bls. The fine to coarse sands range in color from gray to dark brown in areas that are stained from fuel and waste oil contamination.

Soil hydrocarbon contamination at this site appears to be mainly within the vicinity of the generator maintenance concrete pad area. Contaminated soils were identified based on visual appearance, odor, and VOC field screening results. Heavily contaminated soils were encountered during the VW installation and during all MP installations. Contaminated soils exhibited hydrocarbon odors and were visibly stained from dark, oily fuel. Soil gas VOC readings ranged from 200 to 2,800 ppmv of total hydrocarbons at the MPs and VW locations.

Soil samples for laboratory analysis were collected from the stainless steel handauger bucket during the installation of the permanent MPs. Soil samples were collected from 5.5 feet bls at MPA and MPB, and the VW. Soil samples were screened for



# MONITORING POINT CONSTRUCTION SPECIFICATIONS

Monitoring Point No.	Borehole Depth (FT)	Screen Interval (Feet BLS)
MPA-3.0 MPA-5.5	5.5	2.5-3.0 5.0-5.5
MPB-3.0 MPB-5.5	5.5	2.5-3.0 5.0-5.5
MPC-3.0 MPC-5.5	5.5	2.5-3.0 5.0-5.5
BACKGROUND MOI	NITORING POINT	
MP-3.0 MP-5.0 (LOCATED AT FACE	5.5 UTY 1748)	2.5-3.0 5.0-5.5

DRAWING IS NOT TO SCALE

AS-BUILT PERMANENT
MONITORING POINT CONSTRUCTION DETAIL
FACILITY 44625D

CAPE CANAVERAL AFS, FLORIDA

ENGINEERING-SCIENCE, INC. Denver, Colorado



# LEGEND

- INLET AIR FILTER
- VACUUM GAUGE (in H2O) (%)
- BLOWER GAST/70 SCFM © 20 INCHES H20 REGENERATIVE W/1HP DRIVE MOTOR (D)
- AUTOMATIC PRESSURE RELIEF VALVE 4
- MANUAL PRESSURE RELIEF (BLEED) VALVE -- 1 1/2" GATE (D)
- IN-LINE 1 1/2" GATE VALVE 6
  - PRESSURE GAUGE (in H2O) (P)
- POWER SWITCH/TIMEP BOX TEMPERATURE GAUGE (F) **®** 6
- BREAKER BOX (115V/SINGLE PHASE/30 AMP) (2)
- (11) AIR VELOCITY MEASURE PORT

# DRAWING IS NOT TO SCALE

# AS-BUILT BLOWER SYSTEM FOR AIR INJECTION

CAPE CANAVERAL AFS,, FLORIDA

ENGINEERING—SCIENCE, INC. Denver, Colorado

VOCs using a GasTech/Trace-techtor® hydrocarbon analyzer to determine the presence of contamination and to select soil samples for laboratory analysis.

Soil samples were shipped via Federal Express® to Pace, Inc. in Huntington Beach, California for chemical and physical analyses. Each of the soil samples were analyzed for BTEX, iron, alkalinity, TKN, pH, phosphates, percent moisture, and grain size distribution. Soil gas samples were shipped via Federal Express® to Air Toxics, Inc. in Folsom, California for TVH and BTEX analyses. The results of these analyses are presented in Table 2.1, and the chain-of-custody form is presented in Appendix C.

## 2.3 EXCEPTIONS TO TEST PROTOCOL DOCUMENT PROCEDURES

Test procedures described in the protocol document were used to complete the treatability pilot tests at this site. There was one exception to the Bioventing Pilot Test Work Plan (Part I) at Facility 44625D. A multi-depth MP was constructed rather than a single-depth MP.

# 2.4 FIELD QA/QC RESULTS

Field quality QA/QC samples were not collected or required at this site.

# 2.5 PILOT TEST RESULTS

# 2.5.1 Initial Soil Gas Chemistry

Prior to initiating any air injection, all MPs were purged until oxygen levels had stabilized, and initial oxygen, carbon dioxide, and TVH concentrations were sampled using portable gas analyzers, as described in the technical protocol document (Hinchee et al., 1992). Table 2.2 describes initial soil gas chemistry at the site. At MPA, MPB, MPC, and at the VW, microorganisms had completely depleted soil gas oxygen supplies, indicating significant biological activity and soil contamination. MPBG, located at nearby Facility 1748, had near-atmospheric levels of oxygen and carbon dioxide. This indicates that the uncontaminated soils in the area do not exert any significant oxygen demand due to natural organic biodegradation or abiotic reactions.

# 2.5.2 Air Permeability

An air permeability test was conducted according to protocol document procedures. Air was injected into the VW for 4 hours at a rate of approximately 64 scfm and an average pressure of 21 inches of water. Steady-state pressure levels were achieved in all MPs after only 3 minutes of air injection. Table 2.3 provides the steady-state pressures at each MP. Due to this rapid pressure response, the steady-state method of determining air permeability was selected. A soil gas permeability value of 79 darcys, typical for sandy soils, was calculated for this site. A radius of pressure influence of approximately 30 feet was observed at this site.

# 2.5.3 Oxygen Influence

The radius of oxygen increase in the subsurface resulting from air injection into the VW during pilot testing is an important design parameter for full-scale bioventing systems. Optimization of full-scale and multiple vent well systems requires pilot

TABLE 2.1
SOIL AND SOIL GAS LABORATORY ANALYTICAL RESULTS
FACILITY 44625D

Analyte (Units) <sup>a</sup> /	Sample Location-Depth (feet below land surface)			
Soil Gos Hudrasarhans	<u>VW 3-6.5</u>	MPA-5.5	MPC-5.5	
Soil Gas Hydrocarbons TVH (ppmv)	350	510	330	
Benzene (ppmv)	0.26	0.80	ND	
Toluene (ppmv)	0.19	0.32	0.10	
Ethylbenzene (ppmv)	NDb/	ND	ND	
Xylenes (ppmv)	1.3	2.2	1.2	
0.377.1	<u>VWC-5.5</u>	MPA-5.5	MPB-5.5	
Soil Hydrocarbons TRPH (mg/kg)	8,440	8,000	15,000	
Benzene (mg/kg)	ND	ND	ND	
Toluene (mg/kg)	ND	ND	ND	
Ethylbenzene (mg/kg)	ND	ND	ND	
Xylenes (mg/kg)	1.3	1.7	ND	
Soil Inorganics				
Iron (mg/kg)	1,900	1,220	1,020	
Alkalinity (mg/kg as CaCO <sub>3</sub> )	270	233	293	
pH (units)	9.2	9.1	9.2	
TKN (mg/kg)	76	80	66	
Phosphates (mg/kg)	210	160	200	
Soil Physical Parameters				
Soil Temperature (°F)d/	NSc/	70.8	NS	
Moisture (% wt.)	7.7	6.1	5.1	
Gravel (%)	0.2	3.8	0.5	
Sand (%)	98	93.2	96.5	
Silt (%)	0.8	0.7	0.5	
Clay (%)	2.6	2.2	2.5	
Ciay (70)	2.0	2.2	2.3	

a/ TRPH = total recoverable petroleum hydrocarbons; TPH = total petroleum hydrocarbons; mg/kg = milligrams per kilogram, ppmv = parts per million, volume per volume; CaCO<sub>3</sub> = calcium carbonate; TKN = total Kjeldahl nitrogen.

b/ ND = not detected.

c/ NS = not sampled.

d/ Soil temperature at MPC-5.5 was 70.5°F.

TABLE 2.2
INITIAL SOIL GAS CHEMISTRY
FACILITY 44625D
CAPE CANAVERAL AFS, FLORIDA

Sample Location	Depth (ft)	O <sub>2</sub> (%)	CO <sub>2</sub> (%)	Field TVH (ppmv) <sup>a/</sup>	Lab TVH (ppmv) <sup>b/</sup>	Lab TRPH (mg/kg) <sup>c/</sup>
MPA	5.5	0.0	15.8	260	510	8,000
MPB	5.5	0.0	15.9	280	NSc/	15,000
MPC	5.5	0.0	16.9	200	330	NS
vw	3-6.5	0.0	16.0	200	350	8,440
MPBG	3.0	20.5	0.5	0.0	NS	NS
	5.5	20.3	0.7	0.0	NS	NS

a/ Gastech/Trace-techtor® field screening results.

b/ Laboratory results.

c/ NS = not sampled.

# TABLE 2.3 MAXIMUM PRESSURE RESPONSE AIR PERMEABILITY TEST

# FACILITY 44625D

		Distance :	from injec	tion well	(VW) (fee	et)
		10 [PA]		20 PB)	30 (MF	
Depth (feet)	3.0	5.5	3.0	5.5	3.0	5.5
Time (min)	10.0	10.0	10.0	10.0	10.0	10.0
Max Press (inches H <sub>2</sub> 0)	3.3	3.6	2.2	2.4	0.08	0.18

testing to determine the volume of soil that can be oxygenated at a given flow rate and vent well screen configuration.

Table 2.4 presents the change in soil gas oxygen levels that occurred after 4 hours of continuous air injection. This period of air injection, at approximately 64 scfm, produced changes in soil gas oxygen levels at least 30 feet from the VW. Based on this rapid change in oxygen levels, it is anticipated that the radius of oxygen influence for a long-term bioventing system at this site will exceed 30 feet. During the startup of the extended pilot test system, the air injection rate will be reduced to the minimum flow required to provide oxygen within a radius of 30 feet from the VW. Based on similar systems constructed in sandy soils, it is anticipated that an air injection rate of approximately 20 scfm will be sufficient for extended testing.

# 2.5.4 In Situ Respiration Rates

The *in situ* respiration test was performed by injecting a mixture of air (oxygen) and approximately 5 to 6 percent helium (inert tracer gas) into MPA-5.5, MPB-5.5, and MPC-5.5 for a 20-hour period. Oxygen loss and other changes in soil gas composition over time were then measured at each MP. Oxygen, TVH, carbon dioxide, and helium were measured for a period of approximately 80 hours following air injection. The measured oxygen losses were then used to calculate biological oxygen utilization rates. The results of *in situ* respiration testing for MPA, MPB, and MPC are presented in Figures 2.6 through 2.8. Table 2.5 provides a summary of the oxygen utilization rates.

Because helium is a conservative, inert gas, the change in helium concentrations over time can be useful in determining the effectiveness of the bentonite seals above MP screened intervals. Figures 2.6 through 2.8 compare oxygen utilization and helium retention. Although the helium recovery at this site was slightly erratic, the loss of helium from the soil was less than the steady rate of oxygen utilization. Because helium will diffuse approximately three times faster than oxygen due to oxygen's greater molecular weight, the measured oxygen loss is primarily the result of bacterial respiration and not due to oxygen diffusion or oxygen loss from leaks in the MPs.

Oxygen loss occurred at moderate rates ranging from 0.004 %/min at MPB-5.5 to 0.008 %/min at MPC-5.5. Based on test results an estimated 1,640 at MPB-5.5 to 3140 at MPC-5.5 mg of fuel per kg of soil can be degraded each year at this site. This estimate is based on an average air-filled porosity of approximately 0.19 liter per kg of soil, and a conservative ratio of 3.5 mg of oxygen consumed for every 1 mg of fuel biodegraded. Additional information on the calculation for fuel biodegradation can be found in Section 5 of the protocol (Hinchee et al., 1992). Actual rates will vary and could be reduced during the rainy season due to higher soil moisture and reduced air-filled porosity.

# 2.5.5 Potential For Air Emissions

The long-term potential for air emissions from full-scale bioventing operations at this site is considered low because of the low injection rate proposed for extended testing (<20 scfm) and the fact that initial soil gas total BTEX level was less than 4 ppmv. Health and safety monitoring was conducted during the four hour air permeability tests using a GasTech® hydrocarbon analyzer sensitive to 1-ppmv

**TABLE 2.4** 

# INFLUENCE OF AIR INJECTION AT VENT WELL

# ON MONITORING POINT OXYGEN LEVELS


# FACILITY 44625D


MP	Distance From VW (ft)	Depth (ft bls)	Initial O <sub>2</sub> (%)	Final O2 (%) Permeability Test*
A	10	3	0.0	NS <sup>b/</sup>
B	20	3	0.0	NS
C	30	3	0.0	19.0
A	10	5.5	0.0	NS
B	20	5.5	0.0	NS
C	30	5.5	0.0	19.9

a/ Reading taken at end of 4 hours of air injection.

b/ Not sampled.

Facility 44625D (Generator Shop - Drum Storage Area), MPA-5.5 Oxygen and Helium Concentrations Cape Canaveral AFS, FL Respiration Test





Facility 44625D (Generator Shop - Drum Storage Area), MPB-5.5

Cape Canaveral AFS, FL

Oxygen and Helium Concentrations

(oxygen utilization rate) k= 0.008272 %/min. Percent Oxygen Percent Helium Facility 44625D (Generator Shop - Drum Storage Area), MPC-5.5 6.0 5.0 4.0 3.0 2.0 1.0 0.0 Oxygen and Helium Concentrations 5.00 ο. Cape Canaveral AFS, FL 4.00 Time (minutes x 1000) 3.00 2.00 1.00 0.00 20.0 18.0 16.0 0.0 14.0 12.0 10.0 8.0 6.0 4.0 2.0 Percent Oxygen

# **TABLE 2.5**

# **OXYGEN UTILIZATION RATES**

# FACILITY 44625D

Location	O <sub>2</sub> Loss <sup>a</sup> / (%)	Test <sup>b/</sup> Duration	O <sub>2</sub> Utilization <sup>c/</sup> Rate (%/min)
MPA-5.5	20.0	4,920	0.0067
MPB-5.5	20.0	4,920	0.0043
MPC-5.5	19.9	3,240	0.0083

a/ Actual measured oxygen loss.

b/ Elapsed time from beginning of test to time when minimum oxygen concentration was measured.

c/ Values based on best-fit lines (Figures 2.6 through 2.8).

increases in volatile hydrocarbons. No emissions in excess of 1 ppmv were detected in the breathing zone during the 4-hour period. Because the potential for air emissions is highest during this initial hour of air injection, the long-term emission potential is considered low.

# 3.0 FACILITY 44625E

# 3.1 Pilot Test Design and Construction

The following sections describe the final design and installation of the bioventing system at Facility 44625E, the generator shop maintenance area. An air injection VW was installed on December 23, 1993 by ES and Groundwater Protection, Inc. (Drilling Division), both of Orlando, Florida. Three permanent pressure/vapor MPs were installed on December 30, 1993. The VW construction, MP installations, and soil sampling were directed by Mr. Steve Archabal, the ES site manager. The following sections describe in more detail the final design, installation, and testing of the bioventing system at this site.

One VW, three permanent MPs, and a blower unit in a weatherproof enclosure were installed at Facility 44625E. The locations of the MPs and VW followed the original work plan found in Part I of this report. A multi-depth MP construction was used at the site. Monitoring depth screen intervals of 2.5 to 3.0 and 5.0 to 5.5 feet bls were installed at this site. Figure 3.1 depicts the test area with the locations of the MPs, VW, and blower at Facility 44625E. Figure 3.2 shows a hydrogeologic cross section oriented in an east-west direction.

# 3.1.1 Air Injection Venting Well Construction


The VW was installed within the vicinity of the generator maintenance area, as shown in Figure 3.1. The VW was constructed in visibly contaminated, oxygen-depleted soils. Soils encountered during the VW construction were darkly stained and emitted strong hydrocarbon odors.


The installation of the VW was in accordance with typical AFCEE work plan protocols (Hinchee et al., 1992). On the date of the VW installation, water level at Facility 44625E was approximately 6.5 feet bls.

The VW was constructed using 4-inch diameter, Schedule 40 PVC casing with 5 feet of 0.03-inch slotted PVC screen installed from 3 to 8 feet bls. The annular space between the well casing and borehole was filled with 6/20 graded silica sand to approximately 1 foot above the well screen. A 1-foot layer of bentonite pellets were placed above the sand and hydrated in place. A 1-foot cement grout seal was placed over the bentonite to ground surface. The top of each VW was completed with a flushmount steel well manhole set in a 2x2-foot concrete pad. Figure 3.3 shows the as-built construction details for the VW. The geologic soil boring log for the VW installations is provided in Appendix B.

# **3.1.2 Permanent Monitoring Points**

Three permanent multi-depth MPs were installed at Facility 44625E on December 30, 1993. MPs CA4-MPA, CA4-MPB, and CA4-MPC were installed at respective distances of 10, 20, and 30 feet from the VW location. A permanent background MP,





94DN0344, 04/05/94 at 10:52

MPBG, was installed at Facility 1748 (see Figure 1.1). All permanent MP boreholes were advanced using a decontaminated stainless steel hand auger. MPA, MPB, and MPC were screened at 2.5 to 3.0 and 5.0 to 5.5 feet bls.

All three permanent MPs were constructed using 0.5-inch-diameter PVC screens and casing installed in 4-inch-diameter boreholes. Each MP was constructed using a 6-inch section of 0.02-inch slotted, Schedule 40 PVC screen and Schedule 80 PVC casing. The screened interval was surrounded by a filter pack of 6/20 graded coarse silica sand.

Thermocouples were also installed at the screened intervals of MPA and MPC only. Bentonite pellets, hydrated in place, were used to seal the annulus around each MP riser above the gravel pack and between the screened intervals. A 1-foot grout seal was placed over the bentonite to ground surface. The top of each MP PVC riser was completed at ground surface with a brass ball valve and a 0.25-inch brass hose barb. Each MP was completed at the surface with an 8-inch, flush-mounted steel manhole set in a concrete 2x2-foot pad. The lid to the manhole was set approximately 1 inch above ground surface, and the concrete base was sloped toward the edges to promote drainage of surface water away from the MP. Figure 3.4 shows a typical permanent MP construction detail.

#### 3.1.3 Blower Unit Installation and Operation

A 1-horsepower Gast® regenerative blower unit was installed at Facility 44625E for the initial and extended pilot tests. The Gast® blower was installed in a weatherproof enclosure and electrically wired for 115-volt, 30-amp power.

Air is supplied by the blower through a 1.5-inch-diameter, aboveground steel header pipe that is attached to the VW. Figure 3.5 shows the configuration, instrumentation, and specifications for the blower and air injection system.


Prior to departing from the site, ES personnel provided O&M instructions to AFS personnel. A copy of these instructions is provided in Appendix A.

#### 3.2 SOIL AND SOIL GAS SAMPLING RESULTS

Soils at Facility 44625E consist of loose, fine- to coarse-grained sand, with shell fragments. This soil profile was consistent across the site at each boring location from ground surface to below the water table surface, which typically averages 6 to 8 feet bls. The fine to coarse sands range in color from light gray to dark brown in those areas that are stained from fuel and waste oil contamination.

Soil hydrocarbon contamination at this site appears to be confined mainly within the generator maintenance pad area. Contaminated soils were identified based on visual appearance, odor and VOC field screening results. Heavily contaminated soils were encountered during the VW installation and during all MP installations. Contaminated soil exhibited hydrocarbon odors and was visibly stained from dark oily fuel. Soil gas VOC readings ranged from 280 to 14,800 ppmv of total hydrocarbons at the MP and VW locations.

Soil samples for laboratory analysis were collected from the stainless steel handauger bucket during the installation of the permanent MPs. Soil samples were collected from 5.5 feet bls at MPA, MPB, and the VW. Soil samples were screened for VOCs



#### MONITORING POINT CONSTRUCTION SPECIFICATIONS

Monitoring Point No.	Borehole Depth (FT)	Screen Interval (Feet BLS)
MPA-3.0 MPA-5.5	5.5	2.5-3.0 5.0-5.5
MPB-3.0 MPB-5.5	5.5	2.5-3.0 5.0-5.5
MPC-3.0 MPC-5.5	5.5	2.5-3.0 5.0-5.5
BACKGROUND MO	NITORING POINT	
MP-3.0 MP-5.0	5.5	2.5-3.0 5.0-5.5
(LOCATED AT FAC	IUIY 1/48)	TT 4

DRAWING IS NOT TO SCALE

AS-BUILT PERMANENT
MONITORING POINT CONSTRUCTION DETAIL
FACILITY 44625E

CAPE CANAVERAL AFS, FLORIDA

ENGINEERING-SCIENCE, INC. Denver, Colorado



94DN0341, 04/05/94 at 10:52

II-41

## LEGEND

- INLET AIR FILTER
- VACUUM GAUGE (in H2O) (3)

**©** 

BLOWER

(<u>a</u>-

/ AIR FILTER

(9)

FROM ATMOSPHERE

- BLOWER GAST/70 SCFM @ 20 INCHES H20 REGENERATIVE W/1HP DRIVE MOTOR (m)
- AUTOMATIC PRESSURE RELIEF VALVE •
- MANUAL PRESSURE RELIEF (BLEED) VALVE -- 1 1/2" GATE (b)
- IN-LINE 1 1/2" GATE VALVE 6
- PRESSURE GAUGE (in H2O) TEMPERATURE GAUGE (F) (e)
  - POWER SWITCH/TIMEP BOX (e)

VENT WELL (INJECTION)

9

**(** 

- BREAKER BOX (115V/SINGLE PHASE/30 AMP) @
- (11) AIR VELOCITY MEASURE PORT

# DRAWING IS NOT TO SCALE

# AS-BUILT BLOWER SYSTEM FOR AIR INJECTION

CAPE CANAVERAL AFS,, FLORIDA

ENGINEERING—SCIENCE, INC. Denver, Colorado

using a GasTech/Trace-techtor®, hydrocarbon analyzer to determine the presence of contamination and to select soil samples for laboratory analysis.

Soil samples were shipped via Federal Express® to Pace, Inc. in Huntington Beach, California for chemical and physical analyses. Each of the soil samples were analyzed for TRPH, BTEX, iron, alkalinity, TKN, pH, phosphates, percent moisture, and grain size distribution. Soil gas samples were shipped via Federal Express® to Air Toxics, Inc. in Folsom, California for TVH and BTEX analyses. The results of these analyses are presented in Table 3.1, and the chain-of-custody form is presented in Appendix C.

#### 3.3 EXCEPTIONS TO TEST PROTOCOL DOCUMENT PROCEDURES

Test procedures described in the protocol document were used to complete treatability pilot tests at this site. There was one exception to the Bioventing Pilot Test Work Plan (Part I) at Facility 44625E. Multi-depth rather than single-depth MP screens were installed to more effectively monitor oxygen influence at this site because soil contamination was present throughout the unsaturated zone.

#### 3.4 FIELD QA/QC RESULTS

Field QA/QC samples were not collected or required at this site.

#### 3.5 PILOT TEST RESULTS

#### 3.5.1 Initial Soil Gas Chemistry

Prior to initiating any air injection, all MPs were purged until oxygen levels had stabilized, and initial oxygen, carbon dioxide, and TVH concentrations were sampled using portable gas analyzers, as described in the technical protocol document. At all MP screened intervals, microorganisms had completely depleted soil gas oxygen supplies, indicating significant biological activity and soil contamination. The uniformity of zero oxygen levels at this site is primarily the result of the vertical and horizontal uniformity of soil contamination. Table 3.2 describes initial soil gas chemistry at the site. A background MP located at nearby Facility 1748 had near-atmospheric levels of oxygen and carbon dioxide. This indicates that uncontaminated soils at the same depth do not exert significant oxygen demand due to natural organic biodegradation or abiotic reactions.

#### 3.5.2 Air Permeability

An air permeability test was conducted according to protocol document procedures. Air was injected into the VW for 3 hours at a rate of approximately 55 scfm and an average pressure of 29 inches of water. Steady-state pressure levels were achieved in all MPs after approximately 10 minutes of air injection. Table 3.3 provides the steady-state pressures at each MP. Due to this rapid pressure response, the steady-state method of determining air permeability was selected. A soil gas permeability value of 50 darcys was calculated for this site. At this flow rate, the radius of pressure influence will exceed 30 feet. Based on this test, it appears that a reduced flow rate of 20 scfm will be adequate for providing oxygen to the entire pilot test area.

TABLE 3.1
SOIL AND SOIL GAS LABORATORY ANALYTICAL RESULTS
FACILITY 44625E

#### CAPE CANAVERAL AFS, FLORIDA

Analyte (Units) <sup>a/</sup>		le Location-Depth low ground surface	e)
	<u>VW 3-6.5</u>	MPA-5.5	MPC-5.5
Soil Gas Hydrocarbons	0.05	220	500
TVH (ppmv)	0.25	320	590
Benzene (ppmv)	NDb/	ND 0.002	0.15
Toluene (ppmv)	ND	0.093	1.5
Ethylbenzene (ppmv)	ND	ND	0.96
Xylenes (ppmv)	ND	0.90	5.6
	<u>VW-5.5</u>	MPA-5.5	MPB-5.5
Soil Hydrocarbons			
TRPH (mg/kg)	33	5,380	22,200
Benzene (mg/kg)	ND	ND	ND
Toluene (mg/kg)	ND	0.6	ND
Ethylbenzene (mg/kg)	ND	ND	1.3
Xylenes (mg/kg)	ND	0.87	20
Soil Inorganics			
Iron (mg/kg)	1,300	894	728
Alkalinity (mg/kg as CaCO <sub>3</sub> )	280	325	455
pH (units)	8.8	9.1	8.5
TKN (mg/kg)	78	63	ND
Phosphates (mg/kg)	250	320	250
Soil Physical Parameters			
Soil Temperature (°F) <sup>d</sup>	NSc/	69.9	NS
Moisture (% wt.)	7.7	5.2	6.2
Gravel (%)	2.4	0.3	0.1
Sand (%)	95.4	97.2	97.8
Silt (%)	0.3	0.8	0.5
Clay (%)	2.5	3.4	2.6
Ciuj (70)	2.3	J.T	2.0

a/ TRPH = total recoverable petroleum hydrocarbons; TPH = total petroleum hydrocarbons; mg/kg = milligrams per kilogram, ppmv = parts per million, volume per volume; CaCO<sub>3</sub> = calcium carbonate; TKN = total Kjeldahl nitrogen.

b/ ND = not detected.

c/ NS = not sampled.

d/ Soil temperature at MPC-5.5 was 70.1°F

**TABLE 3.2** INITIAL SOIL GAS CHEMISTRY FACILITY 44625E CAPE CANAVERAL AFS, FLORIDA

Sample Location	Depth (ft)	O <sub>2</sub> (%)	CO <sub>2</sub> (%)	Field TVH (ppmv) <sup>a/</sup>	Lab TVH (ppmv) <sup>b/</sup>	Lab TPH (mg/kg) <sup>b/</sup>
MPA	5.5	0.0	16.9	120	320	5,380
MPB	5.5	0.0	16.0	260	NS	22,200
MPC	5.5	0.0	16.0	300	590	NS
vw	3-6.5	11.5	8.0	60	0.25	33
MPBG	3.0	20.5	0.5	0.0	NS	NS
	5.5	20.3	0.7	0.0	NS	NS

Gastech/Trace-techtor® field screening results. a/

Laboratory results. NS = not sampled. ь/

c/

# TABLE 3.3 MAXIMUM PRESSURE RESPONSE AIR PERMEABILITY TEST FACILITY 44625E CAPE CANAVERAL AFS, FLORIDA

	D	istance fro	om injection	on well (V	W) (feet)	)
		lO PA)		20 PB)	3( (MF	
Depth (feet)	3.0	5.5	3.0	5.5	3.0	5.5
Time (min)	10.0	10.0	10.0	10.0	10.0	10.0
Max Press (inches H <sub>2</sub> 0)	4.8	5.0	2.4	2.45	1.15	1.20

#### 3.5.3 Oxygen Influence

The radius of oxygen increase in the subsurface resulting from air injection into the VW is the primary design parameter for full-scale bioventing at this site. Table 3.4 presents the change in soil gas oxygen levels that occurred during 3 hours of air injection. This period of air injection at approximately 55 scfm produced changes in soil gas oxygen levels at a distance of at least 30 feet from the VW. Based on the pressure influence of at least 30 feet, the long-term radius of oxygen influence should also exceed 30 feet. During the start up of the extended pilot test, the air injection rate will be reduced to the minimum flow required to provide oxygen to soils within a 30-foot radius of the VW. This should ensure oxygenation of the entire contaminated soil volume within the boundaries of the study area.

#### 3.5.4 In Situ Respiration Rates

The *in situ* respiration test was performed by injecting a mixture of air (oxygen) and approximately 6 percent helium (inert tracer gas) into the deep screened interval of each MP (MPA-5.5, MPB-5.5, and MPC-5.5) for a 20-hour period. Oxygen loss and other changes in soil gas composition over time were then measured at each MP. Oxygen, TVH, carbon dioxide, and helium were measured for a period of approximately 104 hours following air injection. The measured oxygen losses were then used to calculate biological oxygen utilization rates. The results of *in situ* respiration testing for MPA-5.5, MPB-5.5, and MPC-5.5 are presented in Figures 3.6 through 3.8. Table 3.5 provides a summary of the oxygen utilization rates.

Because helium is a conservative, inert gas, the change in helium concentrations over time can be useful in determining the effectiveness of the bentonite seals above MP screened intervals. Figures 3.6 through 3.8 compare oxygen utilization and helium retention. Oxygen loss occurred at a moderate rate, averaging 0.0029 %/min. Based on test results, an estimated average 990 mg of fuel per kg of soil can be degraded each year at this site. This estimate is based on an average air-filled porosity of approximately 0.17 liter per kg of soil, and a conservative ratio of 3.5 mg of oxygen consumed for every 1 mg of fuel biodegraded. Actual rates will vary and could be reduced during the rainy season due to higher soil moisture and reduced air-filled porosity.

Although the helium recovery at this site was slightly erratic, the loss of helium from the soil was less than the steady rate of oxygen utilization. Because helium will diffuse approximately three times faster than oxygen due to oxygen's greater molecular weight, the measured oxygen loss is primarily the result of bacterial respiration and not due to oxygen diffusion or oxygen loss from leaks in the MPs.

#### 3.5.5 Potential Air Emissions

The long-term potential for air emissions from full-scale bioventing operations at this site is considered low because of the low injection rate proposed for extended testing (<20 scfm) and the fact that initial soil gas BTEX levels were less than 10 ppmv. Health and safety monitoring was conducted during the 3-hour air permeability tests using a GasTech® hydrocarbon analyzer sensitive to 1-ppmv increases in volatile hydrocarbons. No emissions in excess of 1 ppmv were detected in the breathing zone

TABLE 3.4
INFLUENCE OF AIR INJECTION AT VENT WELL
ON MONITORING POINT OXYGEN LEVELS

#### CAPE CANAVERAL AFS, FLORIDA


**FACILITY 44625E** 

MP	Distance From VW (ft)	Depth (ft)	Initial O <sub>2</sub> (%)	Final O <sub>2</sub> (%) Permeability Test <sup>a</sup> /
A	10	3	0.0	NS <sup>b/</sup>
B	20	3	0.0	NS
C	30	3	0.0	5.0
A	10	5.5	0.0	NS
B	20	5.5	0.0	NS
C	30	5.5	0.0	16.5


a/ Reading taken at end of 3 hours of air injection.

b/ Not sampled.


Facility 44625E (Generator Shop - Maintenance Area), MPA-5.5 Oxygen and Helium Concentrations Cape Canaveral AFS, FL Respiration Test



Facility 44625E (Generator Shop - Maintenance Area), MPB-5.5 Oxygen and Helium Concentrations Cape Canaveral AFS, FL Respiration Test



Facility 44625E (Generator Shop - Maintenance Area), MPC-5.5 Oxygen and Helium Concentrations Cape Canaveral AFS, FL Respiration Test



#### **TABLE 3.5**

#### **OXYGEN UTILIZATION RATES**

#### FACILITY 44625E

#### CAPE CANAVERAL AFS, FLORIDA

Location	O2 Loss*/ (%)	Test <sup>b/</sup> Duration	O2 Utilization <sup>c</sup> Rate (%/min)
MPA-5.5	19.5	6,240	0.0031
MPB-5.5	16.2	6,240	0.0026
MPC-5.5	17.2	6,240	0.0028

a/ Actual measured oxygen loss.

b/ Elapsed time from beginning of test to time when minimum oxygen concentration was measured.

c/ Values based on best-fit lines (Figures 3.6 through 3.8).

during the three hour air injection test. Because the potential for air emissions is highest during this initial hour of air injection, the long-term emission potential is considered low.

#### 4.0 RECOMMENDATIONS

Initial bioventing tests at these three sites at Cape Canaveral AFS indicate that oxygen has been depleted in the contaminated soils, and that air injection is an effective method of increasing aerobic fuel biodegradation. AFCEE has recommended that air injection begin at the three pilot test areas to determine the long-term radius of oxygen influence and the effect of time, available nutrients, and changing temperatures on fuel biodegradation rates.

Small, 1-horsepower regenerative blowers have been installed at the three sites to continue air injection at a rate of approximately 10 to 20 scfm per well. Following regulatory approval to proceed, the extended 1-year pilot test will begin at each site. Six months after the extended test begins, ES will return to the site to conduct a repeat respiration test. A final respiration test will be conducted, and soil and soil gas samples will be collected from the site to determine the degree of remediation achieved during the first year of *in situ* treatment.

Based on the results of the first year of pilot-scale bioventing, AFCEE will recommend one of three options:

- 1. Upgrade, if necessary, and continue operation of the bioventing system for full-scale remediation of the site.
- 2. If final soil sampling indicates significant contaminant removal has occurred, AFCEE may recommend additional sampling to confirm that cleanup criteria have been achieved.
- 3. If significant difficulties or poor results are encountered during bioventing at this site, AFCEE may recommend removal of the blower system and proper abandonment of the VW and MPs.

#### 5.0 REFERENCES

- Hinchee, R.E., S.K. Ong., R.N. Miller, D.C. Downey, and R. Frandt. 1992. Test Plan and Technical Protocol for a Field Treatability Test for Bioventing. Prepared for USAF Center for Environmental Excellence. May.
- CH<sub>2</sub>M Hill, 1992. Hazwrap, Martin Marietta Phase I Contamination Assessment, Cape Canaveral Air Force Station, Orlando, Florida. April/July.

#### APPENDIX A

### SYSTEM MAINTENANCE INSTRUCTIONS

#### APPENDIX A

#### SYSTEM MAINTENANCE

#### A.1 BLOWER/MOTOR MAINTENANCE

The blower and motor are relatively maintenance free. There is no lubrication required because the blower and motor have sealed bearings. If a blower system is in need of repair, please contact Steve Archabal at (303) 831-8100.

#### A.2 FILTER MAINTENANCE

To avoid damage caused by passing solids through the blower, an air filter has been installed inline before the blower. By design, Gast® regenerative blowers are able to ingest small quantities of particles without damage. However, continuous ingestion of solids will damage or imbalance the impellers. The inline air filter will prevent solids from entering the blower, and is rated at 99 percent efficiency to 10 microns.

The filter element is a polyester cloth that can be cleaned and reused, or replaced. The filter should be checked weekly for the first 2 months of operation. The air filter should be cleaned or replaced when the pressure difference across the filter reaches 15 to 20 inches of water. It is the responsibility of Patrick AFB and Cape Canaveral AFS to determine the best schedule for filter cleaning and/or replacement, depending on the results of the initial observations.

The filter can be checked after turning off the blower system. To remove the filter, loosen the clamps, lift the metal top off the air filter, and lift the air filter from the metal housing. When replacing the filter, be careful that the rubber seals remain in place. The filter is manufactured by Solberg Manufacturing, Inc. in Itasca, Illinois. Their phone number is (708) 773-1363. The filters can also be obtained through Fluid Technology, Inc. in Denver, Colorado. The contacts there are Mr. Bob Cook and Mr. Greg Sparks; they can be reached at (303) 233-7400. It is recommended that Cape Canaveral AFS keep at least three spare air filters; one for each site.

#### A.3 BLOWER PERFORMANCE MONITORING

To monitor the blower performance, vacuum, pressure, and temperature will be measured. These data will be recorded on the data collection sheets provided. All measurements will be taken at the same time while the system is running.

#### A.3.1 Pressure/Vacuum

Record the pressure and vacuum readings directly from the gauges in inches of water. Record the measurements on the data collection sheet provided.

#### A.3.2 Temperature

Record the temperature readings directly from the gauges in degrees Fahrenheit. Record the measurements on the data collection sheet provided.

#### A.4 MONITORING SCHEDULE

The following monitoring schedule is recommended for this system. During the initial months of operation, more frequent monitoring is recommended to ensure that any start up problems are quickly corrected. Data collection sheets have been provided to record the system data.

Site	Monitoring Item	Monitoring Frequency
Facilities:		
1748 44625D and 44625E Cape Canaveral AFS	Blower vacuum/ pressure and temperature	Weekly

TOWER INTESTIGNATION STREET OF THE COMMENT STREET

SITE

СНЕСКЕОВУ							
сомментѕ							
BLOWER FUNCTIONING UPON ARRIVAL							
FILTER CHANGED (Y or N)							
OUTLET PRESSURE (IN. WATER)							
OUTLET TEMP. (DEGREES F)			٠				
INLET VACUUM (IN. WATER)							,
тіме							
DATE							

#### APPENDIX B

GEOLOGIC BORING LOGS,

TEST DATA, AND CALCULATIONS

#### GEOLOGIC BORING LOG

BORING NO.:	CA2-VW	CONTRACTOR:	GROUNDWATER PROTECTION	DATE SPUD:	12/23/93
CLIENT:	AFCEE	RIG TYPE:	AUGER	DATE CMPL:	12/23/93
JOB NO:	722409.26	DRLG METHOD:	HSA	<b>ELEVATION:</b>	+6 FT - MSL
LOCATION	CAPE CANAVERAL AFS	BORING DIA:	12*	TEMP:	60-70°P
GEOLOGIST	SRA	DRLG FLUID:	NONE	WEATHER:	PARTLY CLOUDY
COMMENTS					

Oepth	Pro-	USCS	Geologic Description	Samples		Sample	Blow	Remarks	
(IL.)	me		Geologic Description	No.	Dopth (ft)	Туре	Counts	TIP = Bkgrad/Reading(ppm	
			Sand, f-m, tr. silt, lt-dk gray						
1									
	( )		×						
2		SP-			0-3.5	G		TVH=2.0 (2')	
_			•		0-3.5		1	1 V H = 2.0 (2 )	
	. : . :	SM				,			
3				VW					
4			Sand, f-c, lt-dk gray, v moist, strong fuel odor					TVH=250 (4')	
					3.5-4.5	G		200(1)	
_	4				5.5-4.5	-			
5	` /							•	
	,								
6	۵ _		Sand, $f-c$ , $lt-dk$ gray, $v$ moist, strong fuel odor					TVH=420 (6')	
		SP			4.5-8.0			@ 6.5 ft.	
7	- 0								
							1		
. !	D :								
8						G		Total Depth = 8.0 ft	
9									
10									
				-					
				1				•	
11				-					
							1		
12			·						
Ì									
13				1					
				1					
				-					
14									
15								·	
			sl - slight v - very NO/NS-No Odor/	f - fine		D	Spr	SPOON SAMPLE	
			tr - trace kt - light No Stain	m - medium			j orlli	SPOONSAMPLE	
			sm - some dk - dark HSA-Hollow Stem	c - coarse			CUT	TNG SAMPLE	
			& - and bf - buff Auger  @ - at brn - brown SSA-Solid Stem	BH - Bore Hole SAA - Same As A	bove	G	GRAI	BSAMPLE	
			w - with blk - black Auger	M.S.L Mean Se			JURA	DOMNELE	
							EST, V	VATER TABLE	

#### **GEOLOGIC BORING LOG**

BORING NO.:	CA3-VW	CONTRACTOR:	GROUNDWATER PROTECTION	DATE SPUD:	12/23/93
CLIENT:	AFCEE	RIG TYPE:	AUGER	DATE CMPL:	12/23/93
JOB NO:	722409.26	DRLG METHOD:	HSA	<b>ELEVATION:</b>	+6 FT - MSL
	CAPE CANAVERAL AFS	BORING DIA:	12"	TEMP:	60-70 °F
GEOLOGIST	SRA	DRLG FLUID:	NONE	WEATHER:	PARTLY CLOUDY
COMMETE					

		USCS		Sample		Sample	Blow	Remarks
(ft.)	file		Geologic Description	No.	Depth (ft)	Турс	Counts	TIP = Bkgrnd/Reading(pps
			Sand, f-m, dk brn stained, fuel odor					
1								
2	. ;	SP-			0-4.0	G		77/11 - 100 (01)
	17				0-4.0	G		TVH=109 (2')
		SM						
3				vw				
4						G		TVH=160 (4')
	. ` '		Sand, f-c, lt-dk gray, w/sm shell fragments, strong petroleum					
5	-		3 3				:	
	D '							
	1.							
6	٩	SP		j				TVH=275 (6')
	1.				4.0-8.0	G		@ 6.5 ft.
7	_ '							
				}				
8	0 -							Total Depth = 8.0
							1	Total Depth = 8.01
•	}							
9								
10								
11								
				1				
12				1			1	
14				-				
13							İ	
14								
				]				
15				1				
	1	1,	st – slight v – very NO/NS-No Odor/	f C	1	_	1	
				f – fine m – medium		D	) SPLE	r spoon sample
				c - coarse	•		CUT	TING SAMPLE
				BH - Bore Hole SAA - Same As A	bove	G	GRA	BSAMPLE
				M.S.L Mean Se			1 244	
							EST. V	VATER TABLE

#### GEOLOGIC BORING LOG

BORING NO.:	CA4-VW	CONTRACTOR:	GROUNDWATER PROTECTION	DATE SPUD:	12/23/93
CLIENT:	AFCEE	RIG TYPE:	AUGER	DATE CMPL:	12/23/93
JOB NO:	722409.26	DRLG METHOD:	HSA	<b>ELEVATION:</b>	+6FT - MSL
LOCATION	CAPE CANAVERAL AFS	BORING DIA:	12*	TEMP:	60−70 °F
GEOLOGIST	SRA	DRLG FLUID:	NONE	WEATHER:	PARTLY CLOUDY
COMMENTS					

Depth	Pro-	USCS		Samples		Sample	Blow	Remarks
(ft.)			Geologic Description	No.	Depth (ft)	Турс	Counts	TIP = Bkgrnd/Reading(ppm)
	4		Sand, f-m, dk brn stained, fuel odor					
1								
2		SP-			0-4.0	G		TVH=5.0 (2')
٦								(-)
		SM						
3				vw				
4						G		TVH=23 (4')
			Sand, f-c, lt-dk gray, w/sm shell fragments, strong fuel odor					
5	₫.							
	. /							
6		SP						TVH=101 (6')
	` A				4.0-8.0	G		@ 6.5 ft.
7								
	1					·		
8								Total Depth = 8.0 ft.
Ť			·					
9		1						
10			·					
	İ							
11					1			
12								
	1			· ·				
				1				
13	-			1				
				-	1			
14	1			1				
15								
	1	•	sl – slight v – very NO/NS-No Odor/	f - fine		D	SPLI	TSPOONSAMPLE
			tr - trace kt - light No Stain	m - medium			_	
			sm – some dk – dark HSA–Hollow Stem & – and bf – buff Auger	c - coane BH - Bore Hole			] cui	TING SAMPLE
			@ - at brn - brown SSA-Solid Stem	SAA – Same As	Above	G	GRA	BSAMPLE
			w - with blk - black Auger	M.S.L. – Mean S	ca Level		- Ber	WATED TABLE
			ENGINEEDING_SCIE				- E31.	WATER TABLE

ENGINEERING-SCIENCE

#### CAPE CANAVERAL AFS - Facility 1748 **Biodegradation Rate Calculations**

calculated data enter data

Formula:

$$K_h = K_0 \times 1/100\% \times A \times D_0 \times C$$
 Where:

 $K_{b}$  = fuel biodegradation rate

 $K_0 = O_2$  utilization rate (%/min.)

A = volume of air/kg soil

$$D_0 = O_2$$
 density = 1340 mg/L

 $C = Carbon/O_2$  ratio for hexane mineralization = 1/3.5

Test Results:

 $K_o = max.$  observed rate moisture content

0.002721 | %/min. 11.8 %

Assume:

Soil properties for mixed grain sand, loose Specify from

Table 1.4 (Ref. Foundation Engineering, Peck, Hanson, and Thornburn,

John Wiley Press, 1974)

Porosity:

Unit weight (dry):

n = 0.40 gd = 1.59 e = n/(1-n) = 0.67 G = 2.65

Void ratio:

Specific gravity:

Calculate A = Air filled volume  $(V_a)$ /unit wt.

Solving for 1 liter of soil

a)  $V_{v} = n * 1 L$ 

0.4 liters  $V_v = \text{void volume}$ 

b) 
$$S_r = Gw/e$$
 
$$S_r = \boxed{0.47}$$

 $S_r = degree of saturation$ 

c) 
$$V_w = S_r \times V_v$$

$$V_w = \boxed{ 0.19} \text{ liters } V_w = \text{volume of water}$$

e) Bulk density =  $^g$ d + ( $V_w \times ^g w$ ) = 1.8 kg/l soil


f)  $A = V_a/Bulk density =$ 

0.117 i air/kg soil

 $K_{b} = K_{a} \times 1/100\% \times A \times D_{a} \times C \times 525,600 \text{ min/yr} = 640 \text{ mg TPH/year}$ 

					_		Resr	Respiration lest	1681					
						Facil	ty 174	8 - Ba	Facility 1748 - Base Cafeteria	teria				
						ပ	oe Ca	Cape Canaveral AFS,		F				
						Elapsed								
		Days		Hrs elapsed	Days	Time			Total					
Monitoring		Elapsed		(fractional	Elapsed	(min. x			Hydro-			Trend of O2/	New	
-	Date	(frac. days) Time	a E	days)		1000)	05%	CO2%	carbon	Helium	Comments	Time	x-values	~
T	94	0.00 12:00	5:00	00.0	0.00	0.00	20.0	00.0	0	4.3	Soil temperature = 68.5 degrees F.	19.928456	0	0.002721
	01/25/94	0.00 14:00	00.	0.08		0.12	19.7	0.00	0	4.4	Soil temperature = 71.2 degrees F.	0.9886591	6.96	
	01/25/94	0.00 16:00	2:00	0.17		0.24	19.5	0.00	0	4.5	Soil temperature = 70.1 degrees			
T	01/25/94	0 00 52:00	00.0	0.42	L		1	0.00	0	4.3	Soil temperature = 71.3 degrees F.			
	01/28/04	1 00 10.00	00.0	-0.08	1_			1	0	4.1	Soil temperature = 72.3 degrees F.			
T	01/26/04	4 00 22.00	00.0	0 42				_		L	Soil temperature = 71.8 degrees F.			
1	01/27/94	2 00 10:00	00.0	-0.08					0	3.2				
	01/27/94	2 00 2	00.6			3.48	6.6	4.00	10	2.8	Soil temperature = 72.1 degrees F.			
	01/28/94	3 00 10:00	00.0				7.3	5.00	20	2.3	Soil temperature = 72.5 degrees F.			
	01/28/04	3 00 22.00	00.0		3.42			6.00	20	2.0	Soil temperature = 72.6 degrees F.			
	100/07/0	4 00 4	00.00	-0.08					20	1.6	Soil temperature = 73.0 degrees F.			
	100,000	00.00	00.0	-0 17	1					1.4	Soil temperature = 72.8 degrees F.			
MP-A-5.5	1000	00.0	3	5		5		_						
MPR.F.F.	01/25/94	0 00 12:00	5.00	00.0	0.00	0.00	20.0	0.00	0	4.2		20.006308	0	0.002453
	01/25/94	0.00 14:00	4:00	0.08				0.00	0	4.2		2.9349678	96.9	
Ī	01/25/94	0 00 16 00	00.9	0.17				0.00	0	4.4				
	01/25/94	0.00 22:00	5:00	0.42	0.42	09.0	18.8	0.00	0	4.2				
	01/26/94	1.00 10:00	00:0	-0.08	0.92	1.32	16.8	0.80	0	4.2				
	01/26/94	1.00 22:00	2:00	0.42	1.42	2.04	15.0	1.80		3.8				
	01/27/94	2.00 10:00	00:0	-0.08	1.92	2.76	12.9	2.70	0	3.4				
	01/27/94	2.00 22:00	5:00	0.42	2.45		11.2	3.60	0	3.0				
	01/28/94	3.00 10:00	00:0	-0.08	2.92	4.20	9.5	4.50	10	2.6				
	01/28/94	3.00 22:00	2:00	0.42	3.42	4.92	7.7			2.1				
	01/29/94	4.00 10:00	0:00	-0.08	3.92	5.64		6.80	10	1.8				
	01/30/94	5.00 08:00	8:00	-0.17	4.83	6.96	3.6	8.30	10	4.4				
										$\perp$	T	100,000		0 000748
	01/25/94	0.00 12:00	2:00	0.00							Soli temperature =	1000	10	4
MPC-5.5 01/	01/25/94	0.00 14:00	4:00	0.08							Soll temperature = 72.3 degrees F.	1.0097	0.30	
	01/25/94	0.00 16:00	6:00	0.17			19.6			$\perp$	Soil temperature = /1./ degrees r.			
MPC-5.5 01/	01/25/94	0.00 22:00	2:00	0.42		0.60		- 1			Soil temperature = 72.6 degrees F.			
	01/26/94	1.00 10:00	00:0	-0.08	0.92	1.32	16.5	0.80	٥		4.1 Soil temperature = 74.3 degrees F.			
	01/26/94	1.00 22:00	2:00	0.42	1.42	2.04	14.7	2.00	0	3.7	Soil temperature = 73.1 degrees F.			
	01/27/94	2.00 10:00	00:0	-0.08	1.92	2.76	12.7	3.20	0	3.5	Soil temperature = 74.6 degrees F.			
	01/27/94	2.00 22:00	2:00	0.42	2.42	3.48	10.9	4.00	0	2.8	Soil temperature = 73.6 degrees			
	01/28/94	3.00 10:00	00:0	-0.08		4.20	8.8	4.80	10	2.4	Soil temperature = 74.8 degrees F.			
	01/28/94	3.00 22:00	2:00	0.42		4.92	6.5	5.80	10	_	Soil temperature = 75.2 degrees F.			
T	01/29/94	4.00 10:00	00:0	-0.08					10		1.6 Soil temperature = 75.3 degrees F.			

Respiration Test
Oxygen and Helium Concentrations
Facility 1748 (Base Cafeteria), MPA-5.5
Cape Canaveral AFS, FL



CAPE CANAVERAL AFS - Facility 44625D calculated data **Biodegradation Rate Calculations** enter data  $K_h = K_o x 1/100\% x A x D_o x C$ Formula:  $K_{h}$  = fuel biodegradation rate  $K_0 = O_2$  utilization rate (%/min.) A = volume of air/kg soil  $D_0 = O_2$  density = 1340 mg/L  $C = Carbon/O_2$  ratio for hexane mineralization = 1/3.5  $K_0 = \text{max. observed rate}$ Test Results: MPB-5.5 0.004323 %/min. moisture content Soil properties for mixed grain sand, loose Specify from Assume:

Table 1.4 (Ref. Foundation Engineering, Peck, Hanson, and Thornburn,

2.65

John Wiley Press, 1974)

0.40 Porosity: e = n/(1-n) = G = G1.59 Unit weight (dry): Void ratio:

Calculate A = Air filled volume (V<sub>a</sub>)/unit wt.

Specific gravity:

Solving for 1 liter of soil

a)  $V_v = n * 1 L$ 0.4 liters  $V_v = \text{void volume}$ 

0.2  $S_r = degree of saturation$ 

c)  $V_w = S_r \times V_v$   $V_w =$ 0.08 liters  $V_w = \text{volume of water}$ 

d)  $V_a = V_v - V_{vw}$   $V_a = \boxed{ 0.32} \text{ liters } V_a = \text{volume of air}$ 


e) Bulk density =  $^g$ d + ( $V_w \times ^g$ w) = 1.7 kg/l soil

0.188 I air/kg soil f) A = V<sub>a</sub>/Bulk density =

 $K_b = K_0 \times 1/100\% \times A \times D_0 \times C \times 525,600 \text{ min/yr} = 1640 \text{ mg TPH/year}$ 

				_	Kesp	Respiration lest	est					
					1							
			Facility 4	44625D C	eneral	or Sh	op - Dru	m Stc	Ity 44625D Generator Shop - Drum Storage Area			
				ပ္ပ	Cape Canaveral AFS,	avera	I AFS, FL	_				
				Elapsed								
	Days	Hrs elapsed	osed Days	Time			Total					
Monitoring	Elapsed	(fractional	onal Elapsed	d (min. x			Hydro-			Trend of O2/	New	
Point Date	(frac. days) Time	e days)	(8	1000)	05%	CO2%	carbon	Helium	Comments	Time	x-values	¥
MPA-5.5 01/19/94	0.00 10:00		0.00 0.00	00.00	20.0	0.00	0	5.9	Soil temperature = 64.2 degrees F.	19.924714	0	0.006728
MPA-5.5 01/19/94			0.08 0.08	8 0.12	19.5	0.00	0	6.0	Soil temperature = 67.4 degrees F.	5.392144	2.16	
MPA-5.5 01/19/94	00.0	14:00	0.17 0.17	7 0.24	18.7	0.20	0	5.9	Soil temperature = 69.2 degrees F.			
MPA-5.5 01/19/94	00.0	16:00	0.25 0.25	5 0.36	17.7	0.40	0	6.0	Soil temperature = 70.3 degrees F.			
MPA-5.5 01/19/94	00.0	22:00	0.50 0.50	0 0.72	14.5	09.0	0	6.0	Soil temperature = 70.1 degrees F.			
MPA-5.5 01/20/94	1.00	00:90	-0.17 0.83	3 1.20	10.9	1.60	0	6.0	Soil temperature = 70.5 degrees F.			
MPA-5.5 01/20/94	1.00 14:00		0.17 1.17	1.68	0.8	3.10	0	5.8	Soil temperature = 72.5 degrees F.			
MPA-5.5 01/20/94	1.00 22:00		0.50 1.50	0 2.16	6.5	4.00	0	5.6	Soil temperature = 70.6 degrees F.			
MPA-5.5 01/21/94	2.00 06:00		-0.17 1.83	3 2.64	5.0	4.80	0	5.4	Soil temperature = 71.6 degrees F.			
MPA-5.5 01/21/94	2.00	16:00	0.25 2.25		2.9	5.30	28	4.9	Soil temperature = 72.5 degrees F.			
MPA-5.5 01/22/94	3.00	- 00:80	-0.08 2.92	2 4.20	0.3	7.00	09	4.8	ti			
MPA-5.5 01/22/94	3.00	18:00	0.33 3.33	3 4.80	0.0	8.00	68	4.8	Soil temperature = 72.4 degrees F.			
MPB-5.5 01/19/94	0.00 10:00		0.00 00.00	00.00	20.0	0.00	0	6.0	•	19.961922	0	0.004323
MPB-5.5 01/19/94	00.00	12:00	0.08 0.08	8 0.12	19.7	00.0	0	6.0		-0.7893277	4.8	
MPB-5.5 01/19/94	00.00	14:00	L	7 0.24	19.1	0.10	0	5.8				
MPB-5.5 01/19/94			0.25 0.25	5 0.36		0.20	0	5.9				
MPB-5.5 01/19/94	0.00			0 0.72	17.0	0.40	0	6.0				
MPB-5.5 01/20/94	1.00					0.50	0	5.8				
	1.00					0.90	0	5.8				
	1.00				-	1.50	٥	5.5				
	2.00			2		2.20	0	5.2				
	2.00					2.90	10	4.5				
	3.00					4.50	36	6.4				
MPB-5.5 01/22/94	3.00	18:00	0.33 3.33	3 4.80	0.0	5.50	48	4.2				
MDC 5.6	000	40.00	00 0	0	40	0	-	ď	Soil fermostature = 64.7 degrees F	18 625286	,	0.008272
1						0 40	0	0	= 67.4 degrees	0 757856	0	
	00.0				1.	09.0	0	0	= 70.1 degrees			
	00.0					0.80	0	5.7	Soil temperature = 71.0 degrees F.			
			1		l	1.60	0		Soil temperature = 70.8 degrees F.			
MPC-5.5 01/20/94	1.00 06:00		-0.17 0.83	1.20	7.2	2.60	0	3.9	Soil temperature = 71.0 degrees F.			
MPC-5.5 01/20/94	1.00 14:00		0.17 1.17	1.68	4.3	4.10	15	3.1	Soil temperature = 72.8 degrees F.			
MPC-5.5 01/20/94	1.00	22:00	0.50 1.50	0 2.16	2.4	5.70	40	2.5	Soil temperature = 70.8 degrees F.			
MPC-5.5 01/21/94	2.00 06:00				0.5	7.20	9	1.9				
			2			9.00	40		= 72.6 degrees			
			-0.08 2.92	4.20	0.0	10.70	20	0.	Soil temperature = 71.2 degrees F.			
	_						Ì	İ				

Facility 44625D (Generator Shop - Drum Storage Area), MPA-5.5 Oxygen and Helium Concentrations Cape Canaveral AFS, FL Respiration Test



CAPE CANAVERAL AFS — Facility 44625E<sup>-</sup>

**Biodegradation Rate Calculations** 

enter data

calculated data

Formula:

$$K_{b} = K_{0} \times 1/100\% \times A \times D_{0} \times C$$
 Where

K<sub>k</sub> = fuel biodegradation rate

 $K_0 = O_2$  utilization rate (%/min.)

A = volume of air/kg soil

$$D_0 = O_2$$
 density = 1340 mg/L

 $C = Carbon/O_2$  ratio for hexane mineralization = 1/3.5

**Test Results:** 

 $K_0 = \text{max. observed rate}$ moisture content

0.002629 %/min.

Assume:

Specify from

Table 1.4 (Ref. Foundation Engineering, Peck, Hanson, and Thornburn,

John Wiley Press, 1974)

Porosity:

0.40

Unit weight (dry):

1.59

Void ratio: Specific gravity:

e = n/(1-n) = G = 00.67 2.65

Calculate A = Air filled volume (V<sub>a</sub>)/unit wt.

Solving for 1 liter of soil

a)  $V_v = n * 1 L$ 

0.4 liters  $V_v = \text{void volume}$ 

b) 
$$S_r = Gw/e$$
 
$$S_r = \boxed{ 0.25}$$

 $S_r = degree of saturation$ 

c) 
$$V_w = S_r \times V_v$$
  
 $V_w = 0.1$  liters  $V_w = volume of water$ 

d)  $V_a = V_v - V_{vw}$   $V_a = \boxed{$ 

0.30 liters  $V_a = \text{volume of air}$ 

e) Bulk density =  $^g$ d + ( $V_w \times ^g w$ ) = 1.7 kg/l soil


f)  $A = V_a/Bulk density =$ 

0.176 | air/kg soil

 $K_b = K_o x 1/100\% x A x D_o x C x 525,600 min/yr =$ 930 mg TPH/year

				a H	Encliste A	4825E (	ener	ator St	M - ac	inten	ance Area			
			+	3	7	-			_			+		
						ပိ	De Cal	navera	I AFS, I	ب	Cape Canaveral AFS, FL			
						Elapsed								
		Days	1		Days	- 1			Total					
Monitoring	2	Elapsed	1	as	Elapsed	x viiii.	ò	à	Hydro-	1	Trend of O2/	_	New	د
T	9.4	0.00 1	11:00	0.00		1	.1	_	O	6.3	Soil temperature = 64.5 degrees F.	19.783614	0	0.003148
	01/18/94	0.00 13:00	3:00	0.08				_	0	6.2	Soil temperature = 67.8 degrees F.	0.1431622	6.24	
	01/18/94	0.00 15:00	5:00	0.17	0.17				0	6.3	Soil temperature = 68.7 degrees F.			
	01/18/94	0.00	2:00	0.25				0.10	0	6.5	Soil temperature = 69.8 degrees F.	-		
	01/19/94	1.00 01:00	1:00	-0.42	1	0.84		L	0	6.8	Soil temperature = 69.1 degrees			
	01/19/94	1.00 09:00	00:6	-0.08	ł		i		0	6.9	Soil temperature = 68.6 degrees F.			
	01/19/94	1.00 17:00	7:00	0.25					0	6.1	Soil temperature = 70.5 degrees			
	01/19/94	1.00 23:00	3.00	0.50	!				0	5.5	Soil temperature = 70.7 degrees F.			
	01/20/94	2.00 0	2:00	-0.17					0	5.3	Soil temperature = 69.6 degrees F.			
MPA-5.5	01/20/94	2.00 1	2:00	0.17	1	3.12		6	0	5.0	Soil temperature =			
	01/20/94	2.00 23	23:00	0.50	1				0	8.4	Soil temperature = 70.0 degrees F.			
	01/21/94	3.00 07:00	2:00	-0.17	1				0	4.6	Soil temperature = 69.8 degrees F.			
	01/21/94	3.00 17:00	7:00	0.25				5.60	10	3.9	Soil temperature = 70.7 degrees F.			
MPA-5.5	01/22/94		9:00	-0.08	1				16		Soil temperature = 69.6 degrees F.			
	01/22/94		19:00	0.33	1	6.24	0.5	80	20	6	Soil temperature = 71.2 degrees F.			
					1									
MPB-5.5	01/18/94	0.00 11:00	1:00	0.00	0.00	0.00	20.0	0.00	0	6.2		19.576106	0	0.002629
	01/18/94	0.00	13:00	0.08	I	0.12	19.8	0.00	0	6.2		3.1729708	6.24	
MPB-5.5	01/18/94	0.00 15:00	2:00	0.17	0	0.24	19.2	0.10	0	6.3				
	01/18/94	0.00	00:2	0.25	0	0.36	19.0		0	6.6				
	01/19/94	1.00 01:00	90	-0.42	o	0.84			0	6.9				
MPB-5.5	01/19/94	1.00 09:00	00:6	-0.08	o	1.32	- 1		٥	6.7				
	01/19/94		8	0.25		1.80		- 1	٥	6.7		1		
1	01/19/94	1.00 23:00	00	0.50	-	2.16	- 1		0	6.3				
MPB-5.5	01/20/94		8	-0.17	-	2.64			0					
1	01/20/94	2.00 15:00	2:00	0.17	Ni.	3.12	11.0		0	6.3		+		
	01/20/94	2.00 2	3.00	0.50	αi	3.60	6	N	0	6.1				
	01/21/94	3.00	02:00	-0.17	ci.	4.08	8.9		0	5.9		1		
MPB-5.5	01/21/94		17:00	0.25	3.25	4.68	7.2		10					
1	01/22/94	4.00 09:00	00:6	-0.08	6	5.64	5.1		2	5.4				
	01/22/94		00.6	0.33	4	6.24	3.8	4.40	10	5.3		-		
	01/18/94	0.00 11:00	00	00.00	0	0.00	20.0	00.0	0	6.1	Soil temperature = 66.2 degrees F.	19.439069	0	0.002899
MPC-5.5	01/18/94		3:00	0.08	0	0.12	19.8		0		Soil temperature = 68.1 degrees F.	1.3515318	6.24	
	01/18/94		5:00	0.17	ı	0.24	19.3		0		Soil temperature = 68.9 degrees F.			
	01/18/94		00:	0.25		0.36	19.0		0		Soil temperature =	_		
	01/19/94		00:	-0.42	0.58	0.84	17.2		0	6.9	Soil temperature			
	01/19/94		00:	-0.08	0.92	1.32	15.2	0.70	0		Soil temperature = 68.6 degrees F.			
	01/19/94	1.00 17:00	00:	0.25	1.25	1.80	13.7		0					
	01/19/94	1.00 23:00	8	0.50	1.50	2.16	12.3		0	6.4	Soil temperature = 70.8 degrees F.			
MPC-5.5	01/20/94	2.00 07:00	00:	-0.17	1.83	2.64	11.0	1.30	٥	6.2	Soil temperature = 69.6 degrees F.			
1	01/20/94	2.00 15	8	0.17	2.17	3.12	9.7	2.00	0		Soil temperature =	1		
	01/20/94	2.00 23	00	0.50	2.50	3.60	4.8	2.50	0	5.9	Soil temperature = 70.3 degrees F.	-		
1	01/21/94	3.00 07	8	-0.17	2.83	4.08	7.1	3.00	0			1		
	01/21/94		8	0.25	3.25	4.68	5.5	3.30	8		Soil temperature	1		
MPC-5.5	01/22/94	4.00 09:00	8	-0.08	3.92	5.64	3.8	4.20	2	5.4	Soil temperature = 70.2 degrees F.	+		
	70/00/10			-	7	70 9					-			

Facility 44625E (Generator Shop - Maintenance Area), MPA-5.5 Oxygen and Helium Concentrations Cape Canaveral AFS, FL Respiration Test



## APPENDIX C CHAIN OF CUSTODY FORMS

中でにた推 Time Time 4 Date 44625E 148 Remarks 44625 6 00 0 d 0 Printed GREG LURAVIC Lab job No. Page \_ ISIOW PACE Received by Signature 7 Received by Company — Signature Company Printed. **Analysis Required** S THE ASSURANCE OF GUALITY ×20 Time Date Time 148 Number of Confainers R 18ms Reason DROP OFF FED W W M 3 3 3 3 3 m Relinquished by Relinquished by DENVER, Co. 80290 Manager: Doug Downey - ES SITE MANAGER: STEVE ARCHAGA Project Name/Number: DE268.26.08 Signature. Company. Signature. Company NONE NONE NONE NONE NONE NONE NONE NONE Printed\_ Reason. Printed. NONE Preservation Temp | Chemical Time Airbill No.: 8645062436 Date 4°C 400 4°C 1400 4°C 4°C 400 5.5 1434 500 SO GLASS/8 0Z 4ºC 5.5 43/9 1520 SO GUES /8 02,4°C Š GLASS/8 07. GLASS/8 OF GLASS/802. FED GLASS/802 GASS/802. GlAS/8 02 GLASS/8 02 Ship Date: 1/3/94 Type/Size of Container RESULTS  $\epsilon_{\times}$ 09 Contract/DO No.: Company ENGINEERING \_\_ Company FED Shipment No.: Ship Method: **(**) Received by (CED) 136 Signature AFCEE Sample Matrix 12/50/ts 1000 SO 20 174 1330 SO 1726 SO SO 05 00 41 E/08/1 5.5 1100 So 5.5 12/3/2 160 So REPORT 1030 Southern California Regional Office 의 팀 1657 SUITEGOO ENGINFERING-SCIENCE, INC. 1320/13 FACILITY Huntington Beach, CA 92649 Signature & Youry . Lucketh 138pm Printed STEVEN R. ARCHARM Log Page Reason SKIP TO LAB Comments PLEASE TEL: (714) 892-2565 FAX: (714) 890-4032 Client: AFCEE BIOVENTING PILOT 5.5 5.5 □ PACE, Incorporated 5.5 5702 Bolsa Avenue 5,5 SED 5,0 CA3-MPB-5.5 5:0 CA4-VW-5.5 S.O. CA4-MPA-56 5.0 2,0 CA3-VW-5.5 5:0 5,0 5,0 CA3-MPA-5.515.0 SBD Relinquished 433 PER 700 BROADWAY Puller CA2-MPA-55 CA2-MPB-5.5 CA2-VW-5.5 CA4-MPB-5.5 303, 831-8100 Field Sample Number Minnesota Regional Office 1710 Douglas Drive North SBD: Sample Beginning Depth SED: Sample Ending Depth Minneapolis, MN 55422 SO - Soil
SE - Sediment
WG - Groundwater
WS - Surface Water
DC - Drill Cuttings
AG - Soil Gas
WQ - Field Quality Control Sample (TB, EB, AB) TEL: (612) 544-5543 FAX: (612) 525-3377 Sampler's Signature □ PACE, Incorporated Log Date: Collection Date Log Time: Collection Time Sample Matrix: Laboratory: Cooler Number Address: EGEND FAX: (

	F QUALITY
	ASURANC
S.A. Contraction	

135471

CHAIN-OF-CUSTODY RECORD Analytical Request Requested Due Date: NO.C.M.AL Pace Project Manager Pace Project No. Pace Client No. Project Name / No. 740104.500 P.O. # / Billing Reference 75 - 33/7 Report To: THERESA LEAHY ANALYSES REQUEST **PRESERVATIVES** Bill To: Sampled By (PRINT): Address Phone Client

TIME MATRIX PACENO.

12-30-93

Date Sampled

Sampler Signature

Sou

CA2-VW-S.S

10:

107

(BIO-VENT

VIA FEO EX FWY FULL

FED EX

Additional Comments

ACCEPTED BY AFFLIATION

九子等奏以管 あるから

000058

חדכונו חכרו דתוכ הכתועתם חממ



135472

CHAIN-OF-CUSTODY RECORD Analytical Request Requested Due Date: Alox 19.14 REMARKS Pace Project Manager DILLE Pace Project No. Pace Client No. 501 P.O. #/ Billing Reference 75-33/7 Project Name / No. 7 4 U / L' + Report To: THE SE (1) LE ANALYSES REQUEST PRESERVATIVES AOV <sup>E</sup>ONH OS2H ОИРВЕЅЕВУЕD OF CONTAINERS ON. 炎疾或 30-53 7 Date Sampled PACE CA3-VW-5. (A3-MPA-S. Sampled By (PRINT): Sampler Signature Address Client Phone

פרב סבערבסרב פוחב בחם ואוכדטוורדוראופ

1-4 1600

VIM FLULX

VIA FEU EX

Additional Comments

000068



CHAIN-OF-CUSTODY RECORD Analytical Request

135473

PACE

Client

Address

Phone

Sampled By (PRINT):

Sampler Signature

Date Sampled

12.30-93

SAMPLE DESCRIPTION

CA4-VW-5.5

2011

CA4-MPA-S.S CA+-MPB-S.S

40

0 -

AFCEE

0

**セナイ/0 ナカ** 

REMARKS

AOV <sup>E</sup>ONH OS2H

JUPRESERVED

OF CONTAINERS

\*Requested Due Date: NUNSMY)

Project Name / No. 740104.502 P.O. #/Billing Reference 75-33/7

**PRESERVATIVES** 

Pace Project Manager

Pace Client No.

Report TO: 1HERESA LEAHY

Pace Project No.

RELINQUISHED BY AFFILIATION ACCEPTED BY AFFLIATION DATE

VIA FED EX

Additional Comments

UIA FEO EX

-4 1600

SEE REVERSE SIDE FOR INSTRICTIONS

から 人間の事をある。

# CHAIN OF CUSTODY RECORD

BLONDINGER COLOR CELL NO.   ACCES BOUGHTHON PLOTTESTS   Processory Active Section   Processor									1			T			, 1	$\neg$			1			T	1	17/45				_
ENGNEERING SCIENCE, INC.  PENGNEERING SCIENCE, INC.  PROPRIED TO TESTS  PROPRIED TO THE STATE OF		LTD. RAVINE ROAD, SUITE		Bob Freeman	( <b>916)</b> 985-1000	•			LTY 17	,		> FACILITY 44625.			> FAULTY 44625E									stochy seals present 1911.		e, C - Composite Sample	CE, INC.	
ENGNEERING SCIENCE, INC.  PENGNEERING SCIENCE, INC.  PROPRIED TO TESTS  PROPRIED TO THE STATE OF	hip To:	AIR 1	FOLS	Attn:			Matrix		AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	AIR	S S		ıb Sampl	CIEN 0 · Den	-8100
ENGINEERING-SCIENCE, INC.  AFCEE BIOVENTHIO PILOTTESTS  TO BE SHOWED A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL  BESTS A PACE CA	<u>σ</u>						Sample Type	ပ ပ																Reme		Q.Gr	ING-S	03) 831-
ENGINEERING-SCIENCE, INC.  AFCEE BIOVENTHIO PILOTTESTS  TO BE SHOWED A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL  BESTS A PACE CA	F							15.7	"HE	746	11	″⊱/dı	7/5/G	1.16	11/1/3	-								71m• 1∪,45	TIme		NEER dway, S	၅
ENGINEERING-SCIENCE, INC.  AFCEE BIOVENTHIO PILOTTESTS  TO BE SHOWED A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL, FL  BESTS A PACE CANAVERAL  BESTS A PACE CA	servalite.	•••	is Required					1,5	Ø	Ø,	9.08	Ö	Ö	3		0				•				/ etad	Date/		ENG!	
ENGINEERING-SCIENCE, INC.  Bases: CAPE CANAVERAL, FL   Samplet(s); (Signaline)  Samplet(s); (Sig	P.		Analys		<u></u>																						17	
ENGINEERING-SCIENCE, INC.  1700 BROADWAY, SUITE 800 20:11-1100 ES JOSD NO. 772.408-76080 ES JOSD NO. 772.408-76080 ES JOSD NO. 772.408-76080 ES JOSD NO. 772.408-76080 ES JOSD NO. 772.408-76080  ES JOSD NO. 772.408-76080  ES JOSD NO. 772.408-76080  ES JOSD NO. 772.408  ES JOSD NO. 772.408  ES JOSD NO. 772.408  ES JOSD NO. 76.408  ES JOSD NO. 76.408  ES JOSD NO. 76.608  ES JOSD NO. 76.	L		NC				ञ्ज	×	XX	XIX.	X X.	XX	XX	XX.X	XΧ	ХX	-							ATZ	sture)			
ENGINEERING-SCIENCE, INC.  1700 BROADWAY, SUITE 800  500-187-187-187-187-187-187-187-187-187-187		币几							_	1	_	_	-	_	_		-							ngis): (q	by: (Sign			
ENGINEERING-SCIENCE, INC.  1700 BROADWAY, SUITE 800 2021-1310  ES JOSD NO. 772.408-76080  ES JOSD NO. 772.408  ES JOSD N	TESTS	AL)	άm σ				30																	oratory	oralory	•		
ENGINEERING-SCIENCE, INC.  1700 BROADWAY, SUITE BOO SCIENCE, INC.  1800 TIMP BROADWAY, SUITE BOO SCOOLS BOO SCIENCE, INC.  1800 THIN BROADWAY, SUITE BOO SCOOLS BOO SCIENCE, INC.  1800 BROADWAY, SUITE BOO SCIENCE, INC.  1800 THIN BROADWAY, SUITE BOO SCOOLS BOO SCIENCE, INC.  1800 BROADWAY, SUITE BOO SCIENCE, INC.  1800 BROADW		AVER	174	200	_		,						•						4					ed for Lat	ed for La		Field File	
ENGINEERING-SCIENCE, INC. 1700 BROADWAY, SUITE BOO 02030300 0204084, SUITE BOO 02030300 0203031-8100  ES JOB NO. 72.408-26080  DE268. 2. 0.08  Sampler(s): (Signsture)  11494 1340 CA 2- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 4- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 4- 11494 1520 CA 3- 11494 1520 CA 4- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 3- 11494 1520 CA 4- 11494 15	NOVENT	CAN	1.ES.	1	0	7	)		7	5		,	•		7	10								Heclev JAL	Rocle		ordinator	
ENGINEERING-SCIENCE, INC.  1700 BROADWAY, SUITE BOO DEIVER, COLORADO 80230  5020-8311-8100  ES JOB NO. 72.2 408-26080  DE268. 2. 0.08  Sampler(s): (Signsture)  11494 1240 C. A.2-  11494 1320 C. A.2-  11494 1520 C. A.2-  11494	AFCEE E	APE (	ciliz	2	0	Z.	ription	80	١	-5,	3	3	5.5	8	-5.	5								/ Пт. 120	/ TIme		8 to: Coc	
ENGINEERING-SCIENCE, INC. 1700 BROADWAY, SUITE BOO DELVER, COLORADO 80230 302-831-8100 ES JOB NO. 722, 408-26080 DE268. 2. 608  Sampler(s): (Signsture)  Sampler(s): (Signsture)  11494 1300 CA2- 11494 1320 CA3- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA4- 11494 1520 CA3- 11494 1520 CA4- 11494 1520 CA3- 11494 152		C	± 7.4 1.7.4	-	(	3	ple Desc	3	NPA	APC	3- U	PA-	Par	- M	1PA	PC.								1/2/4	Date		nt. Copie	
	NC.		ω .			$\mathcal{C}$	Sam	7-7	2- 1	2-1	_	1	1	1-1	١	٤								Mal	2		Shipme	
	ENCE, I	. /	-260	-		Els			CA		A		Œ	2.A.4	A	.A4								1/10	5		e olne gm	
	IG-SCII	SUITE 90	2,08	seture)	t	Se					)	)	)		)	7								Signator	Signatur		Inol Acco	
	TEERIN	OADWAY, COLORI	8.77 7.79	(s): (Sign		/	TIMe		_	1320	1420		1440	1520		1540								yed by:	ind by:		lon: Orig Express !	umber: _
	ENGIR	1700 BR DEHVER 303-831-	ES Job DE 268	Sampler			Date	<u>存</u>	11494	11994	11494		11499	11494	1494	1494								Rellne	Bulliage		Distribu	Alibiliz